

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Authorised
1/1/2021
Penny After Penny
Fdays

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: _____ Third Party

Accident Date : 06.10.2021

Date: **09.10.2021**

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Nissan NV350" Reg. No. GBH4863J Claiming Against Your Insured Reg. No. SKJ180E			
1pc	Front Bumper		595.00 N ✓
12pcs	Front Bumper Clips	3.50	42.00 N ✓
1pc	Front Bumper Corner Retainer LH		152.00 N ✓
1pc	Front Bumper Fog Lamp LH		339.00 N ✓
1pc	Front Bumper Fog Lamp Cover LH		135.00 N ✓
1pc	Headlamp LH		425.00 N ✓
1pc	Headlamp Lock Clip		12.50 N X
1pc	Front Door LH		1,275.00 N ✓
1pc	Front Door Lower Hinge		110.00 N X
1pc	Front Door Lower Step Board		150.00 N ✓
1pc	Front Door Weatherstrip		122.00 N X
1pc	Front Door Rubber Seal Lower		49.00 N X
10pcs	Front Door Trim Board Clips	5.50	55.00 N X
1pc	Front Wheel Cap LH		170.00 N ✓
1pc	Front Wheel Mudflap LH		102.00 N X
1pc	Front Upper Arm		345.00 N X
1pc	Front Lower Arm		230.00 N X
1pc	Sliding Door LH		1,750.00 N ✓
10pcs	Sliding Door Trim Board Clips	5.50	55.00 N X
1pc	Sliding Door Inner Rear Reflective Sticker		45.00 N X
1pc	Rear Wheel Cap LH		165.00 N ✓
1pc	Rear Wheel Mudflap LH		130.00 N X
1pc	Rear Bumper		796.00 N ✓
10pcs	Rear Bumper Clips	3.50	35.00 N ✓
1pc	Taillamp LH		435.00 N ✓
			7,719.50
	Less 10%		771.95
			6,947.55
1pc	Front Door Reg Label		45.00 SN /
1pc	Rear Wheel Bearing ??? Got two Rr Wheel Bearing		120.00 SN X
1pc	Front Wheel Bearing		245.00 SN X
1pc	Front Wheel Hub		596.10 SN X
1pc	Front Lower Arm Ball Joint		108.00 SN X
1pc	Front Knuckle Arm		385.00 SN X
1pc	Front Shock Absorber		145.00 SN X
1pc	Rear Shock Absorber		145.00 SN X

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 09.10.2021

Accident Date : 06.10.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Nissan NV350" Reg. No. GBH4863. Claiming Against Your Insured Reg. No. SKJ180E		
		B/F	8,736.65
			30.00
	To Conduct Electrical Check, Focus Headlamp		601 150.00
	To Dismantle / Transfer Door Fittings / Ancillary Accessories		601 80.00
	To Dismantle / Transfer Sliding Fittings / Ancillary Accessories		nn 140.00 X
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		nn 90.00 X
	To Dismantle / Hi Pressure Press / Replace Front Wheel Bearing		80.00 601
	To Conduct Computerize Wheel Alignment Test		nn 110.00 X
	To Dismantle / Replace Rear Under Carriage to Facilitate Repair		nn 90.00 X
	To Dismantle / Hi Pressure Press / Replace Rear Wheel Bearing		100.00 601
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		900.00 701
	Labour Charge - Panel Beating, Repairing Of Front Corner Panel, Front Door Pillar, Step Panel, Door "B" Pillar, Rear Fender and Parts Replacement		1200
	To Respray Affected Areas (2k Pearl White)		1,400.00
		Total :	11,906.65
			p

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: