						C	OWLOKIDEROKO	
Our Jo	ob Ref	No :	305489205		ENGINEERING			
Date		A Mindage Medical control Medical R	07/10/21	per that the state of the state of		59 L	forDelGro Engineering Pte Lid byang Drive Bingapare 508969 6546 8156	
FINAL	IZATIO	N FORM				rax.	0000 0 100	
То			LKK		umpostos.	Fax		
Attn	Mr		Thevan					
Vehic	le Reg	No. SHA	3950M	CTPL			03/10/2021	
The s	urvey a	nd estimates o	f the repairs of the	above-ment	ioned vehicle	are as follows	-	
1.	The re	epair job shall b	ill to:	N.	TUC		SLR7652K	
2.	The fi	nalized amount	shall be:					
	(a)	Spare Parts a	fter List discount				\$553.08	
	(b)	Labour Charge	es				\$630.00	
		Total for Part	-By-Part Repair (	Cost			\$1,183.08	
	(c.)	Total for Lump	oair (if applicable) osum repair cost a um Repair cost	fter Less:	20%			
<ul><li>3.</li><li>4.</li></ul>	We si	•	riod for repairs:	Correct and		rking days. there is no re	ply from you within 7	
5.		you for your a	ssistance.	A	fina	e confirm the e alized amount nature :	estimates and	
	Name	eture :e  MS. LOKE YY			_		Theran	
		: 621483			- Da		15/10/2/	
	Tel Fax	: 654681					, , , ,	
					_			
For C	micial	Use Only	_					
		Item	Amo	unt	Document Attached Yes or No	Confirm By (Signature)	Remarks	
1. Re	ental R	ate P/Day			YES			
2. Lc	ss of Ir	ncome Paid			NO			
3. Sı	urvey F	ees						
		ch Fee ees (on behalf	\$7.49 /	\$2.00				
5. Mo	edical F driver,	ees (on behalf if applicable)						
	verrun							
Rema	arks:							

## COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA3950M

Make

: Toyota

Model : Prius Date: 04/10/2021

Insurance: NTUC

MVA: MS. LOKE YY

	Amount	Unit Price	Туре	Parts Description / Labour
	552.60 <b>\$499.90</b>			1 REAR BUMPER
١.	\$22.00			10 REAR BUMPER CLIPS
	\$111.60	\$55.80		1 REAR BUMPER SIDE BRACKET LH RH
)	\$82.70			1 REAR BUMPER TOWING COVER
	\$318.80			1 REAR BUMPER REINFORCEMENT
)	\$552.60			1 REAR BUMPER LOWER COVER
)	\$1,587.60			aup zoza
	\$396.90			SUB TOTAL LESS 25%
_	\$1,190.70			DISCOUNTED TOTAL
				BIOCOGNIES TOTAL
)	\$135.70			REAR BUMPER REVERSE SENSOR
	\$135.70			NEW BOIN EN NEVEROL GENOON
				Labour Charge
	\$400.00		1	PANEL BEATING
	\$300.00			SPRAY PAINTING CHARGE
П	\$60.00			REMOVE/ REFIX REVERSE SENSOR
4	\$760.00			TOTAL LABOUR
	\$2,086.40			ESTIMATE TOTAL
	2125.93			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

> Theuan@LHhauto.com 82235769 4/10/21 1645 Plp herpaint photo wp zelays

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting • To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 07.10.2021 Time: 15:15:29

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

**CUSTOMER: 7010045** 

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO **REGN NO**  : 305489205

: SHA3950M : 0000000000 MILEAGE

MAKE

: TOYOTA

MODEL

: PRIUS HYBRID(G4A)

DATE OF REGN DATE/TIME IN

: 05.12.2019 : 03.10.2021 12:35

ACCIDENT DATE : 03.10.2021

JOB / PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2713-G GUARD REAR BUMPER CENTER 1 552.60 25.00 414.45

0002 04-01-0302-2267-G BUMPER PIECE 10 22.00 25.00 16.50

0003 09-01-0302-2005-A REVERSE SENSOR ASSY 1 135.70 10.00 122.13

SUB-TOTAL: 553.08

JOB NATURE

0000 PB

PANEL BEATING SHA3950M

350.00

0001 SP

SPRAYPAINT CHARGE

250.00

0002 20-204

REMOVE/REFIX REVERSE SENSOR

30.00

SUB-TOTAL : 630.00

TOTAL : 1,183.08

MVA NAME & SIG

DATE:

DATE:

AUTHORISED: YES / NO

SURVEYOR NAME & SIGNATURE