

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 2411T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			e
1	FRONT COWL, RIGHT	REUSE	55.00	-
1	FRONT COWL, LEFT	ABRADED / SCRAPED	55.00	55.00
1	SIGNAL LIGHT, LEFT	ABRADED	50.00	50.00
1	FRONT FENDER	ABRADED	60.00	60.00
1	FRONT FENDER SUPPORT "U" BRACKET	SERVICEABLE	22.00	-
1	HANDLEBAR	BENT	58.00	58.00
1	SET BALANCER	ABRADED	38.00	38.00
1	SET MIRROR	DENTED / ABRADED	65.00	65.00
1	CLUTCH LEVER	ABRADED	20.00	20.00
1	BRAKE LEVER	SERVICEABLE	20.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	85.00	-
1	SET STEERING CON / BEARING	NOT NECESSARY	150.00	-
1	PILLION FOOTREST ASSY, LEFT	ABRADED	35.00	35.00
1	RIDER FOOTREST ASSY, LEFT	ABRADED	35.00	35.00
1	SET GEAR SHIFTER	BENT	95.00	95.00
1	PILLION FOOTREST BRACKET	ABRADED	78.00	78.00
1	SET FRONT FORK	TO REPAIR SEE LABOUR	480.00	-
1	BOTTOM CLAMP / UNDER BRACKET	NOT NECESSARY	185.00	-
	LESS 10% DISCOUNT		-158.60	-58.90
			1,427.40	530.10
1	FRONT RIM (LOCAL REPAIR) (SN)	EDGE SCRAPED / BENT	350.00	100.00
	LESS 10% DISCOUNT		-35.00	-
			315.00	100.00
	SPECIAL NETT ITEMS			
1	KAPPA BOX (SN)	ABRADED	350.00	200.00

Report Ref No. CS3/LPC21007599/R1uf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
2	SET FRONT WHEEL BEARING (SN)	NECESSARY	40.00	20.00
			390.00	220.00
	LABOUR			
	TO CHECK WIRING.		30.00	20.00
	TO REPAIR AND SPRAY PAINT THE MAIN STAND.		150.00	120.00
	WORKMANSHIP. INCLUSIVE OF THE REPAIR OF 1 SET FRONT FORK.		350.00	200.00
	TOWING FEE.		70.00	40.00
			600.00	380.00
	GRAND TOTAL		2,732.40	1,230.10

RECOMMENDED COST OF LUMP SUM REPAIRS			1,000.00
(TO ITS PRE-ACCIDENT CONDITION)	以及1995年	Parado de la companya del companya del companya de la companya de	

Report Ref No. CS3/LPC21007599/R1uf3e2-1

MKB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:-This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part, Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.