

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0842/2021/JT
DATE : 12-Oct-21
WIP : 48781

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/10/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

4 days - ok - Jy - 18 Nov 21

OWNER'S NAME : MS LIM GEOK CHOO (LIN YUZHU)
ADDRESS : 127 TAMPINES STREET 11
#08-440
SINGAPORE 521127
TELEPHONE : HP +65 82289550
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210036748
VEHICLE NO : **SMR 8181 J**
MODEL CODE : A6 DESIGN 2.0 TFSI S
MODEL YEAR : 12/04/2021
ENGINE NO : DKY 015270
CHASSIS NO : WAUZZZF27MN051947
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Oct-21
PLACE OF ACCIDENT : 139 TAMPINES ST 11
OPEN SURFACES CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 8181 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$ 250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$ 1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,500.00	\$ 1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK .	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,972.00	\$ 3,022.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 8181 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FORNT BUMPER	1	\$ 2,832.00	\$ 2,265.60
2	FRONT BUMPER FIXING PARTS	1	\$ 650.00	
3	FRONT BUMPER CLOSING ELEMENT - CENTER	1	\$ 222.00	
4	FRONT BUMPER APAPTER - RH	1	\$ 39.00	\$ 31.20
5	FRONT BUMPER MOUNTING BRACKET - RH	1	\$ 111.00	
6	FRONT BUMPER LOWER GRILLE	1	\$ 153.00	
7	FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$ 210.00	\$ 167.60
8	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 434.00	\$ 346.80
9	FRONT BUMPER AIR GUIDE - RH	2	\$ 58.00	\$ 22.56
10	FRONT RADIATOR GRILLE	1	\$ 2,217.00	
11	FRONT BUMPER FOAM FILLER PIECE	1	\$ 226.00	
12	FRONT BUMPER CARRIER	1	\$ 1,012.00	
13	FRONT BUMPER GUIDE SECTION - RH	1	\$ 44.00	\$ 35.12
14	FRONT BUMPER SUPPORT	2	\$ 59.00	
15	FRONT BUMPER BRACKET - RH	1	\$ 54.00	
16	FRONT BUMPER TOP COVER	1	\$ 126.00	\$ 100.40
17	HORN	1	\$ 216.00	
18	HORN BRACKET	1	\$ 47.00	
19	FRONT PARKING AID SENSOR	2	TBC	
20	FRONT PARKING AID SENSOR SEAL	4	\$ 9.00	
SUB TOTAL SPARE PARTS		:	\$ 8,719.00	\$ 2,969.28

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 8181 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 2,969.28
21	FRONT FENDER - RH	1 \$	1,468.00	\$ 1,174.40
22	FRONT FENDER BRACE - RH	1 \$	118.00	\$ 94.40
23	FRONT FENDER BRACKET - RH	1 \$	44.00	
24	FRONT FENDER ATTACHEMENT PART	1 \$	42.00	
25	FRONT WHEEL HOUSING LINER - RH	1 \$	266.00	\$ 212.80
26	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1 \$	71.00	
27	FRONT WHEEL SPOILER - RH	1 \$	166.00	
28	STONE CHIP GUARD - RH	1 \$	51.00	
29	HEADLIGHT MOUNTING - RH	1 \$	118.00	
30	HEADLIGHT - RH	1 \$	8,624.00	\$ 6,899.20
31	HEADLIGHT LIFT CYLINDER - RH	1 \$	198.00	
32	HEADLIGHT WASHER HOSE	1 \$	182.00	
33	FRONT BUMPER WIRING SET	1 \$	577.00	
34	FRONT NO PLATE	S/N \$	60.00	
35	SUPPLEMENTARY	\$	14.00	\$ 10.88
36	SUNDRIES	\$	300.00	\$ 1.76
TOTAL SPARE PARTS		:	\$ 21,018.00	\$ 11,362.72
TOTAL LABOUR CHARGES		:	\$ 5,972.00	\$ 3,022.00
GRAND TOTAL		:	\$ 26,990.00	\$ 14,384.72

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-15/11/21

**Supplementary Estimate - 1**

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.**Date****Service Advisor****Pages****Regn No****Model No**

PA/OD/0842/2021/JT

16-Oct-21

CHANG

1 of 1

SMR 8181 J

AUDI A6 DESIGN 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	SIGN ' CAUTION ' STICKER	\$ 14.00	\$ 10.88
GRAND TOTAL		\$ 14.00	\$ 10.88

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT