



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref: CS/CTI21010544/y3	
3 ANSON ROAD #16-00		Date: 13/10/2021	
SPRINGLEAF TOWERSINGAPORE 079909		Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBN 96B	Veh. Inspected	SGP 205J
Policy No.	DMPCSNW00015982105	Coverage (\$)	0.00
Claim No.	SNM21D205804/C02/SBN96B/T ANCHC	Excess (\$)	0.00
Assign From	JACQUELINE TAN	Assign Date	13/10/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	11/10/2021	Inspection Date	
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD (HQ) 176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			