

Veron Chen (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Wednesday, 18 May 2022 12:09 PM
To: Veron Chen (LKKAUTO)
Subject: Re: EZ 888J---CS/CTI21010547/Kvy3

Dear Veron,

AUDIT CHECK DONE FOR EZ888J, FOUND SOME PARTS PRICES NEED VERIFICATION
& WHEEL ALIGNMENT REPORT IS NEEDED FOR UNDERCARRIAGE PARTS REPLACED.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Wednesday, 18 May 2022 11:46 am
To: Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>
Subject: EZ 888J---CS/CTI21010547/Kvy3

Dear Simon

File for audit check.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)