

Sng Ah Tee Motor & Panel Service Pte Ltd (Co. Reg. No. 200810440N)

Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg, darren@sngahtee.com, janice@sngahtee.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC21P00191800	Date of Loss:	06/10/2021
Vehicle Reg. No.:	SJW4213L	Driveable?	
Driver Age/Info:	45 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LEE YOON WOON	Contact No:	+6592380326
Driver:	LEE YOON WOON		

Make/Model:	TOYOTA PREVIA, 2.4 7-SEATER (A)	Vehicle Reg. Date:	23/03/2010
Vehicle Colour:	BLACK		
Engine No:	2AZH465607	Chassis No:	JTEGD54M00A019313
Odometer:	5 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS

	Amount
Parts	6,720.65
Miscellaneous Items	0.00
Labour	2,510.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,230.65
+ GST 7.00% (S\$)	646.15
Nett Amount (S\$)	9,876.80

This claim is handled by: JANICE CHANG SIEW YIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Stew (LKK)
83228813

90- 111 11
EY 11- ?

L/S

My 11 My
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary damage must be surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Oct 2021)
 Parts: M1-MPV TOYOTA PREVIA 2.4 7-seater (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SJW4213L)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE / BR	0	0.00	*35.00 FS
2	1		*FRT BUMPER / BR	0.00	0.00	*280.00 F
3	2		*FRT BUMPER RETAINER / BR	0.00	0.00	*90.00 F
4	1		*FRT BUMPER LOWER GRILLE / BR	0.00	0.00	*120.00 F
5	1		*FRT BUMPER SPONGE / CR4	0.00	0.00	*70.00 F
6	1		*FRT BUMPER REINFORCEMENT / OD	0.00	0.00	*150.00 F
7	2		*FRT BUMPER SIDE GUIDE / ?	0.00	0.00	*90.00 F
8	1		*FRT BUMPER TOWING COVER LH / M1J	0.00	0.00	*25.00 F
9	2		*FRT FOGLAMP / ?	0.00	0.00	*260.00 F
10	2		*FRT FOGLAMP INNER BRACKET / ?	0.00	0.00	*110.00 F
11	1		*FRT GRILLE / BR	0.00	0.00	*240.00 F
12	1		*FRT GRILLE EMBLEM / CR4	0.00	0.00	*45.00 F
13	1		*FRT GRILLE TOP GARNISH / CR4	0.00	0.00	*150.00 F
14	10		*FRT GRILLE TOP GARNISH CLIP / MC	0.00	0.00	*15.00 F
15	1		*FRT BONNET / OD	0.00	0.00	*240.00 F
16	2		*FRT BONNET HINGE / BT	0.00	0.00	*80.00 F
17	1		*FRT BONNET STAND / X	0.00	0.00	*35.00 F
18	1		*FRT BONNET STAND CLIP / X	0.00	0.00	*1.50 F
19	1		*FRT BONNET SEAL / X	0.00	0.00	*40.00 F
20	1		*FRT BONNET INSULATOR / CR4	0.00	0.00	*150.00 F
21	10		*FRT BONNET INSULATOR CLIP / MC	0.00	0.00	*15.00 F
22	1		*FRT BONNET LOCK / BT	0.00	0.00	*55.00 F
23	2		*FRT FENDER INNERSHIELD / (CR4) TM	0.00	0.00	*200.00 F
24	20		*FRT FENDER INNERSHIELD CLIP / MC	0.00	0.00	*30.00 F
25	2		*FRT HEADLAMP / BR	0.00	0.00	*800.00 F
26	1		*FRT UPPER SUPPORT / OD	0.00	0.00	*180.00 F
27	1		*FRT LOWER SUPPORT / ?	0.00	0.00	*150.00 F
28	2		*FRT SIDE SUPPORT / (CR4) BT	0.00	0.00	*300.00 F
29	1		*FRT BRACE PANEL / BT	0.00	0.00	*45.00 F
30	1		*FRT HORN / ?	0.00	0.00	*65.00 F
31	1		*AIRCON CONDENSER / OD	0.00	0.00	*480.00 F
32	1		*AIRCON FAN BLADE / ?	0.00	0.00	*70.00 F
33	1		*AIRCON FAN MOTOR / ?	0.00	0.00	*180.00 F
34	1		*RADIATOR ASSY / BT	0.00	0.00	*580.00 F
35	1		*RADIATOR FAN MOTOR / ?	0.00	0.00	*180.00 F
36	1		*FAN COWLING / ?	0.00	0.00	*120.00 F
37	1		*AIR INLET CLEANER NO.1 / ?	0.00	0.00	*70.00 F
38	1		*AIR INLET CLEANER NO.2 / ?	0.00	0.00	*70.00 F
39	1		*RESONATOR ASSY / ?	0.00	0.00	*120.00 F
40	1		*COOLANT / MC	0	0.00	*40.00 FS
41	2		*FRT BUMPER REINFORCEMENT BRACKET / ?	0.00	0.00	*140.00 F

F=Franchise part, S=SpcNett.

Sub Total (\$\$) 6,116.50
 + Margin on L,N Items 10.00% (\$\$) 604.15

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (S\$)					6,720.65

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK WIRING	New	30.00 ✓
2	TOP UP AIRCON GAS	New	100.00 ✓
3	TO KNOCK FRT FENDER X2, WELD, REMOVE & FIX ON ABOVE PARTS	New	1000 1,200.00
4	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00 ✓
5	TO DIAGNOSE & RESET FAULT CODE	New	X 180.00
Gross Labour Cost (\$\$)			2,510.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 547G

Vehicle Details

Vehicle No.: SJW4213L
Vehicle to be Exported: No
Intended Deregistration Date: 14 Oct 2021
Vehicle Make: TOYOTA
Vehicle Model: PREVIA 7 SEATER
Primary Colour: Black
Manufacturing Year: 2010
Engine No.: 2AZH465607
Chassis No.: JTEGD54M00A019313
Maximum Power Output: 125.0 kW (167 bhp)
Open Market Value: \$35,783.00
Original Registration Date: 23 Mar 2010
First Registration Date: 23 Mar 2010
Transfer Count: 2
Actual ARF Paid: \$35,783.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 22 Mar 2030
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
PQP Paid: \$35,416.00
COE Rebate Amount: \$29,884.00
Total Rebate Amount: \$29,884.00

The information contained herein is correct as at 07 Oct 2021

OK