Cur I	oh Dof	Ma /	205400400		Administration	OMFORTDELGRO		
	ob Ref	NO ;	305490499		ENGINEERING			
PINALIZATION FORM			19/10/21	-	ComfortDelGro Engineering Pte Li 59 Loyang Drive Singapore 50896 Fax: 6546 8158			
To	LIZA I I	ON FORM	LKK		Fax :			
Attn	Mr Thevan				T dx ,			
Vehicle Reg No. SHA96				PL		13/10/2021		
The s	urvey :	and estimates of	the repairs of the above	e-mentioned vehicle	are as follows:			
1,	The r	epair job shall bi	ill to:	LONPAC	***	YN7605P		
2.	The f	inalized amount	shall be:					
	(a)	Spare Parts af	ter List discount					
	(b)	Labour Charge	es					
		Total for Part-	By-Part Repair Cost			\$0.00		
	(c.)	Lumneum Pan	air (if applicable)					
	(0.)	Total for Lump	sum repair cost after Le	ess:	_			
		Final Lumpsu	m Repair cost			\$3,750.00		
3.	Estim	nated normal per	riod for repairs:	3w	orking days.			
4.		hall treat the al ing days	oove amount as Corre	ct and Confirmed if	there is no re	ply from you within 7		
5.	Than				We confirm the estimates and			
	,	k you for your as	ssistance.	1		stimates and		
	.,,=,,	k you for your as	ssistance.	1	alized amount	stimates and		
		k you for your as	ssistance.	1		stimates and		
		k you for your as	ssistance.	fin		stimates and		
		ature :	<i></i>	fir Si	alized amount gnature:	Thevan		
	Signa	ature :	KE YY	Si Na	alized amount gnature:	J		
	Signa Nam	ature :	KE YY 155	Si Na	alized amount gnature:	Thevan		
For (	Signa Nam Tel Fax	ature :  e : MS. LOI  : 621483	KE YY 155	Si Na	alized amount gnature:	Thevan		
For C	Signa Nam Tel Fax	e : MS. LOI : 621483 : 654681	KE YY 155	Si Na	alized amount gnature:	Thevan		
	Signa Nam Tel Fax Official	ature :  e : MS. LOI  : 621483  : 654681  Use Only	KE YY 1555 56	Si N:	gnature :ame :	Theran 22/10/2/		
1. R	Signa Nam Tel Fax Official	e : MS. LOI : 621483 : 654681	KE YY 1555 56	Si Na Da Document Attached Yes or No	gnature :ame :	Theran 22/10/2/		
1. R	Signa Nam Tel Fax Official	ature :  e : MS. LOI  : 621483  : 654681  Use Only  Item  ate P/Day  ncome Paid	KE YY 1555 56	Document Attached Yes or No	gnature :ame :	Theran 22/10/2/		
1. R 2. L 3. S 4. L	Signa Nam Tel Fax  Dfficial  ental R coss of I urvey F TA Sea	ature :  e : MS. LOI  : 621483  : 654681  Use Only  Item  tate P/Day  ncome Paid  ees  urch Fee	KE YY  555  56  Amount  \$7.49 / \$2.00	Document Attached Yes or No	gnature :ame :	Theran 22/10/2/		
1. R 2. Lu 3. S 4. L 5. M	Signa Nam Tel Fax Dfficial ental R oss of I urvey F TA Sea	ature :  e : MS. LOI  : 621483  : 654681  Use Only  Item  tate P/Day  ncome Paid	KE YY  555  56  Amount  \$7.49 / \$2.00	Document Attached Yes or No	gnature :ame :	Theran 22/10/2/		

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SHA 964T

Make : Toyota

Model

: Prius (G4A)

Date: 13/10/2021
Insurance: LONPAC
MVA: MS. LOKE YY

ty	Parts Description / Labour	Туре	Unit Price	Amount
1 RI	EAR BUMPER			\$499.90
10 RI	EAR BUMPER CLIPS			\$22.00
1 RI	EAR BUMPER LOWER COVER		, ph	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
2 RI	EAR BUMPER UNDER SIDE COVER LH RH		RH <b>√\$232.0</b> 0	(ut \$464.00
1 R	AER BUMPER UNDER SIDE CENTRE COVER		ľ	\$552.60
1 RI	EAR BUMPER TOWING COVER			\$82.70
2 Ri	EAR BUMPER SIDE RETAINER LH RH		\$94.80	\$189.60
1 RI	EAR BUMPER REINFORCEMENT			\$318.80
2 RI	EAR BUMPER SIDE EXTENSION LH RH		\$148.40	\$296.80
2 RI	EAR BUMPER ARM ASSY LH RH		\$139.60	\$279.20
1 RI	EAR END PANEL			\$602.10
1 RI	EAR END PANEL GARNISH			\$165.80
1 RI	EAR WINDSCREEN GLASS WITH MOULDING			\$1,778.30
1 B	ACK DOOR GARNISH SUB ASSY			DE <b>\</b> \$889.70
1 R	EAR TRUNK LID COVER			\$1,126.60
1 RI	EAR TRUNK LID LOCK			\$457.90
1 RI	EAR TRUNK LID GLASS			\$1,569.70
1 RI	EAR TRUNK LID LOGO (PRIUS)			\$60.80
1 RI	EAR TRUNK LID LOGO (HYBRID)			\$52.40
1 RE	EAR TRUNK LID LOGO (TOYOTA STAR)			\$52.90
2 RE	EAR TRUNK LID HINGE LH RH			\$189.50
2 RE	EAR TRUNK LID ABSORBER LH RH			\$287.50
1 R	OOF TOP CENTER COVER – BLACK			\$956.30
1 R	OOF TOP GARNISH SUB LH			<b>\</b> \$136.80
1 R	OOF TOP GARNISH SUB RH			\$136.80
	SUB TOTAL			\$11,721.30
	LESS 25%			\$2,930.33
	DISCOUNTED TOTAL			\$8,790.98
1 RE	EAR BUMPER ADVERTISEMENT LOGO			\$50.00
1 RE	EAR FENDER ADVERTISEMENT LOGO LH			\$100.0Ŏ
1 RE	EAR FENDER ADVERTISEMENT LOGO RH			\$100.0Q
1 RE	EAR NUMBER PLATE WITH TRIM COVER			\$55.00
1 RE	EAR TRUNK LID COMFORT & TEL NO. STICKER			\$60.00
1 RE	EAR TRUNK LID APPS STICKER			\$40.00
1 RE	EAR REVERSE SENSOR		Į	\$135.70
				\$290.70
	bour Charge			•,
	ANEL BEATING			\$1,400.00
SF	PRAY PAINTING CHARGE			\$800.00

Oty Parts Description / Labour	Type	Unit Price	Amount	
CHECK ALL LIGHTING TUFF KOTE REMOVE/REFIX REVERSE SENSOR REMOVE/ REFIX REAR WINDSCREEN GLASS TOTAL LABO	UR		\$80.00 3- \$80.00 3- \$60.00 \$120.00 \$6 \$2,520.00	0
ESTIMATE TO	AL		\$11,601.68	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Therange Lithauto lom
82235769
18/10/21 1600
4
3 day Swp
Lls 9fter repair photo

LKK Auto Consultants hence notify

the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: