

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0839/2021/JT
DATE : 12-Oct-21
WIP : 48626

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/10/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

13 days exclude 2 Sundays

23-Nov-21

OWNER'S NAME : MR NAGAR MEHUL HASMUKH
ADDRESS : 1 FORT ROAD
#15-03
SINGAPORE 439069
TELEPHONE : HP +65 94242099
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210105705
VEHICLE NO : **SNB 6228 U**
MODEL CODE : Q3 1.4 TFSI S TRONIC
MODEL YEAR : 31/8/2021
ENGINE NO : CZD C50059
CHASSIS NO : WAUZZZF34M1156915
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Oct-21
PLACE OF ACCIDENT : REPUBLIC PLAZA CAR PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 6228 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00 \$	360.00
2	TO RENEW RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$	300.00 \$	300.00
3	TO INSTALL SOLAR FILM FOR RHS SIDE 1/4 GLASS.	S/N \$	400.00 \$	400.00
4	TO CARRY OUT WATER SEEPAGE TEST ON 1/4 GLASS.	S/N \$	200.00 \$	150.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00 \$	1,600.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00 \$	1,600.00
TOTAL LABOUR CHARGES		:	\$ 4,460.00	\$ 4,410.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 6228 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 4,410.00
7	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	\$ 280.00
8	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PART REMOVED.	\$	6,400.00	\$ 4,250.00
9	TO REPSRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, DOOR HANDLE, RHS SILL PANEL, DRAIN CHANNEL, ROOF CHANEL, DOOR ENTRANCE AND REAR END PANELLING.	\$	7,000.00	\$ 2,575.00
10	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 18,732.00	\$ 11,707.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 6228 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$	1,634.00	
2	REAR BUMPER FIXING PARTS	1	\$	211.00	
3	REAR BUMPER SPOILER	1	\$	459.00	
4	REAR BUMPER BRACKET - RH	1	\$	48.00	
5	RER BUMPER REFLECTOR - RH	1	\$	41.00	
6	REAR TAIL LIGHT - RH	1	\$	926.00	
7	REAR BUMPER GUIDE SECTION - RH	1	\$	63.00	
8	REAR WHEEL ARCH COVER - LH / RH	2	\$	536.00	\$ 428.80
9	REAR SECTIONAL PART - RH	1	\$	3,388.00	\$ 2,710.40
10	1/4 GLASS	1	\$	614.00	\$ 490.80
11	PRIMER	1	\$	20.00	\$ 15.76
12	REAR WHEEL HOUSING LINER - RH	1	\$	241.00	
13	REAR WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$	101.00	
14	REAR WHEEL SPOILER	1	\$	39.00	
15	REAR DOOR - RH	1	\$	2,909.00	\$ 2,327.20
16	REAR DOOR OUTER SEAL - RH	1	\$	135.00	\$ 108.00
17	REAR DOOR ATTACHMENT PARTS	1	\$	311.00	
18	REAR DOOR CATCH - RH	1	\$	120.00	\$ 96.00
19	REAR DOOR SEAL INNER	1	\$	191.00	
20	SILL PANEL SEAL - RH	1	\$	135.00	
SUB TOTAL SPARE PARTS		:	\$	12,122.00	\$ 6,176.96

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 6228 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	6,176.96
21	REAR DOOR LOWER COVER - RH	1	\$ 257.00	\$	205.20
22	REAR DOOR HANDLE - RH	1	\$ 198.00	\$	158.00
23	REAR DOOR HANDLE CAP - RH	1	\$ 27.00	\$	21.60
24	REAR DOOR MOUNTING BAR - RH	1	\$ 162.00		
25	REAR DOOR BOWDEN CABLE - RH	1	\$ 52.00		
26	REAR DOOR WINDOW REGULATOR - RH	1	\$ 282.00		
27	REAR DOOR WINDOW REGULATOR MOTOR - RH	1	\$ 271.00		
28	REAR DOOR CONTROL UNIT	1	\$ 400.00		
29	REAR TYRE RIM - RH	1	\$ 1,262.00		
30	1/4 GLASS SEALANT	S/N	\$ 100.00	\$	100.00
31	ACRYLIC SEALANT	S/N	\$ 180.00	\$	180.00
32	CRAVITY WAX	S/N	\$ 140.00	\$	140.00
33	STONE CHIP TREATMENT	S/N	\$ 180.00	\$	180.00
34	METAL FILLER POWDER	S/N	\$ 280.00	\$	280.00
35	SUPPLEMENTARY		\$ 311.00	\$	248.80
36	SUNDRIES		\$ 400.00	\$	19.20
TOTAL SPARE PARTS			\$ 16,624.00	\$	7,709.76
TOTAL LABOUR CHARGES			\$ 18,732.00	\$	11,707.00
GRAND TOTAL			\$ 35,356.00	\$	19,416.76

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-10/11/21



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0839/2021/JT 22-Oct-21 CHANG 1 of 1 SNB 6228 U AUDI Q3 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	REAR END PANEL - OUTER	\$ 311.00	\$ 248.80
	GRAND TOTAL	\$ 311.00	\$ 248.80

For Premium Automobiles Pte Ltd

Authorised Signature



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT