



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref:	CS/CTI21010578/Eqy3
3 ANSON ROAD #16-00		Date:	14/10/2021
SPRINGLEAF TOWERSINGAPORE 079909		Code:	CTI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMQ 7274L	Veh. Inspected	SHA 8117U
Policy No.		Coverage (\$)	0.00
Claim No.	SNM21D205854/C02/SMQ7274 L/TANKW	Excess (\$)	0.00
Assign From	TAN KIAN WEI BILLY	Assign Date	14/10/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/10/2021	Inspection Date	14/10/2021
Survey held at	31 Corporation Rd		
Repairer	DING AUTOMOTIVE PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			