

SERVICE PTE LTD

JKIT ROAD 4
 ARTLEY BIZ CENTRE SINGAPORE 417809
 3400 Fax: 67139415
 servicecentre@abwinm9.com Website: www.abwinm9.com
 Reg. No: 201318685G GST Reg. No: 201318685G



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

ESTIMATED COST: HQQ00526

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

Signature: _____ DATE: 14-OCT-2021
 Date: _____ MAKE: KIA
 MODEL: CERATO EX FORTE 1.6L M/T
 CHASSIS NO : KNAFU411LA5162758
 ENGINE NO : G4FC9H329284
 SERVICE ADVISOR : HAZEL
 PAGE : 1 OF 2

SJV629C
MUHAMMAD TAUFIQ BIN MOHD
 BLK 672
 JALAN DAMAI
 #04-35
 SINGAPORE,
 SINGAPORE 410672
 CONTACT NO : 96755945

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1 FRONT BUMPER	700.00 <i>disassemble part.</i>	585.40
1 FRONT BUMPER SPONGE	76.00 X <i>nn</i>	
1 FRONT BUMPER LOWER GRILLE	82.00 X <i>nn</i>	
1 FRONT BUMPER SIDE RETAINER LH	29.00 <i>nn</i>	
1 FRONT BUMPER REINFORCEMENT	448.00 X <i>nn</i>	
1 FRONT FENDER LH	342.00 <i>bt</i>	
1 FRONT FENDER INNER SHIELD LH	86.00 X	
1 HEADLAMP LH	2,369.00 X	
1 HEADLAMP BRACKET LH	0.00 X	
1 FOG LAMP LH	218.00 X	
1 FOG LAMP GARNISH LH	0.00 X	
Sub Total	4,350.00	0.00

SPECIAL NETT	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1 FOG LAMP BRACKET	0.00 X <i>nn</i>	
10 FRONT BUMPER CLIPS	50.00 <i>30</i>	
10 HEADLAMP CLIPS	50.00 X <i>nn</i>	
10 FRONT FENDER INNER SHIELD CLIPS	50.00 <i>10</i>	
Sub Total	150.00	0.00

LABOUR	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1 TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	1,200.00 <i>300.</i>	
1 TO SPRAY PAINT ON AFFECTED AREAS	1,200.00 <i>400</i>	
1 TO APPLY UNDERCOATING FOR RUST PROOFING	180.00 <i>30</i>	
1 TO CHECK WIRING	150.00 X <i>nn</i>	
1 TO CHECK WIRING, CHECK LIGHTING & RESETTING HEADLAMP FOCUS	180.00 X <i>nn</i>	
Sub Total	2,910.00	0.00

Taufiq 97495749 / 62563561
 WP 15/10/21 @ 335pm
 2/3 Resurvey after repair @ 3 days
 Taufiq @ lkkauto.com

~~1620.76~~
~~LS\$1300~~
~~3 DAYS #~~
 1620.76
 LS\$1300
 3 DAYS #