

ASS. REG. BY

Steve

CS/SMR21/10592/E473

ASSIGNMENT

From:

Date:

Estimated Cost:

ON TP / WS / PRE / OD / RES / EVA / INV / MV

To inspect Vehicle No: SMZ 4388P

at Workshop no:

of

Insured: SHB 5021B

Policy No:

Claims No: TAX/10/21/2018

Sum Insured:


Excess:

(Client's Record)

Make of Vch:

(Policy Condition)

Remarks: The vch had commenced its repair at the time of inspection.



Ref. or Market Value:

IDAC Accident Report Consistent? : Yes or No

BIA / PR Sent Consistent? : Yes or No

Est. Repair: 26 days Res.: Yes or No

Sum Sum: % 3 Vol.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Vch No:

SMZ 4388P

Yr Regn: 27/4/21

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make:

Mazda

cc 1496

Colour:

Grey

A/C: Insured / Std / NI / N

Sp. Reading

14372

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

TM ERP 15A: AM 11 06578

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: Nil / S/Rm / STD A/Rm or

Tyre Size:

215/45R18

Ri: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

5

mm

L/Bal:

5

mm

D.O.A.

10/10/21

D.O.A.

15/10/21

Survey held at

Trans Eurokors

Des. of Damages: Fr / Rear / O/S / N/S / VIC / Roof/Top or

The U/S / chassis frame / Body structure affected due to collision

Date / Time

Action / Instruction

MV - 102K

PV - 53,097

NV - 46,903

Note: Repairer willing to undertake repair cost not more than \$48000.

27/10/2021 Submit repair sum \$48000, 26 repair days

(RED \$52996.62; 52%)

Time, Fee, Report



Preli. Report

Days Of Repair: 26

27/10 TYPIST



Final Report

Resurvey No. of Trips:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Inve (\$



Work and (\$

STARS

Private

Others

TOTAL



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

EUROKARS SERVICES

FIRST CAPITAL INSURANCE LTD 38 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877		NAME : ADDRESS : TEL :		WIP : 42684 EXCESS : DATE: 13-Oct-21	
ATTN : MOTOR CLAIMS					
FAX :				CONTACT PERSON : DEREK	
VEH NO :	SMZ4388P	DATE IN :		TYPE OF CLAIM :	THIRD PARTY CLAIM
CHASSIS NO :	JM68P2SAAM1106878	MILEAGE :		POLICY NO. :	
MODEL :	M3 M-HYBRID	DATE REG.:	27-Apr-21		

NATURE OF WORKS

Parts Description							
NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1	FRT BUMPER / BR	1	✓		MBCKA-50-031E8B		\$ 867.30
2	TAPE SEAL / APC	2	✓		MBCKA-50-2G1A		\$ 4.80
3	TAPE SEAL / APC	2	✓		MBDWH-50-2G1		\$ 14.60
4	AIR GUIDE RH FRT X nn	1			MBCKA-50-A20B		\$ 68.20
5	AIR GUIDE LH FRT X nn	1			MBCKB-50-A20B		\$ 68.20
6	RIVET / APC	8	✓		MTK21-50-355		\$ 73.60
7	FASTENER / APC	6	✓		MS515-51-833		\$ 24.00
8	PLATE SEAL RH FRT BUMPER X nn	1			MBCKA-50-1U1A		\$ 15.50
9	PLATE SEAL LH FRT BUMPER X nn	1			MBCKA-50-1V1A		\$ 15.50
10	RETAINER RH FRT BUMPER BP / BR	1	✓		MBCKA-50-0T0A		\$ 20.50
11	RETAINER LH FRT BUMPER BP / BR	1	✓		MBCKA-50-0U0A		\$ 19.50
12	COVER FOG LAMP RH X nn	1			MBCKB-50-C21A		\$ 95.00
13	COVER FOG LAMP LH X nn	1			MBCKB-50-C21A		\$ 95.00
14	RETAINER SMALL RH FRT / BR	1	✓		MBDGF-50-0T6B		\$ 11.00
15	RETAINER SMALL LH FRT / BR	1	✓		MBDGF-50-0U6B		\$ 10.10
16	GROMMET,SCREW / APC	2	✓		MN243-50-0Z1		\$ 10.40
17	GROMMET,SCREW FENDER RH / APC	1	✓		MBCKA-50-0T5		\$ 2.50
18	GROMMET,SCREW FENDER LH / APC	1	✓		MBCKA-50-0U5		\$ 2.50
19	FASTENER / APC	2	✓		MGD7A-50-EA1		\$ 6.40
20	NUT,CLIP / APC	10	✓		MC274-50-133		\$ 37.00
21	FASTENER / APC	2	✓		MB45A-56-146A		\$ 6.00
22	STIFF 'A' BUMPER / APC X nn	1			MBCKA-50-0S0B		\$ 76.10
23	HOLDER,LICENSE PLATE / CNT	1	✓		MBCWB-50-170B		\$ 77.00
24	TAPE,PROTECTOR / APC	3	✓		MBCKA-50-EM1		\$ 14.10
25	CORD FRT BUMPER X nn	1			MBDGI-67-A10		\$ 622.00
26	BRACKET RH BLIND SPOT MONITOR X nn	1			MBCKA-50-153C		\$ 81.20
27	BRACKET LH BLIND SPOT MONITOR X nn	1			MBCKA-50-163C		\$ 81.42
28	MONITOR BLIND SPOT X nn	2			MB0J8-67-Y30C		\$ 3,601.40
29	SENSOR,RADAR-FRONT X nn	1			MB0N2-67-XA0D		\$ 3,002.60
30	RETAINER S.S ULTRASONIC / APC	2	✓		MB0J8-67-UC6		\$ 46.80

34	RETAINER S.S ULTRASONIC	APC	1	✓	MB0L2-67-UC5 13	\$ 47.20
35	RETAINER S.S ULTRASONIC	APC	1	✓	MB0L7-67-UC5 53	\$ 47.20
36	RETAINER S.S ULTRASONIC	APC	1	✓	MB0M5-67-UC5	\$ 4.60
37	RETAINER S.S ULTRASONIC	APC	1	✓	MB0M6-67-UC5	\$ 4.60
38	SENSOR ULTRASONIC CENTER	X nn	2		MB0J7-67-UC1	\$ 380.00
39	SENSOR ULTRASONIC SIDE	X nn	2		MB0J8-67-UC1 2M	\$ 380.00
40	BRACKET RH S.S ULTRASONIC	X nn	1		MBDGG-50-154A	\$ 24.90
41	BRACKET LH S.S ULTRASONIC	X nn	1		MBDGG-50-164A	\$ 24.90
42	COVER TOWING FRT	MIS	1	✓	MBCKB-50-A11	\$ 32.00
43	PLATE SET CENTER FRT BUMPER	X nn	1		MBCKC-50-1C1A	\$ 9.10
44	GARNISH CENTER FRT BUMPER	X nn	1		MBCKA-50-1T4A	\$ 11.00
45	GRILLE RADIATOR FRT	BR	1	✓	MBCKB-50-711	\$ 527.40
46	PLATE SEAL RH FRT GRILLE	X nn	1		MBCKC-50-1U2A	\$ 15.50
47	PLATE SEAL LH FRT GRILLE	X nn	1		MBCKC-50-1V2A	\$ 15.50
48	BRACKET MASCOT FRT	X nn	1		MBCKB-50-721A	\$ 85.50
49	MASCOT FRT WITH SENSOR	X nn	1		MBCKB-51-730A	\$ 705.90
50	CLIP BRACKET MASCOT FRT	APC	2	✓	MG46L-50-EB1	\$ 9.40
51	MOULD CHROME RH FRT	BR	1	✓	MBCKA-50-7J0C	\$ 298.00
52	MOULD CHROME LH FRT	BR	1	✓	MBCKA-50-7K0C	\$ 298.00
53	CLIP MOULD	APC	1	✓	MGSH7-50-EB1	\$ 9.10
54	CAMERA, FRONT	MIS	1	✓	MB0J9-67-RC0	\$ 1,066.80
55	GRILLE, RADIATOR- TOP	CRU	1	✓	MBCKB-50-7E0D2M	\$ 690.80
56	RIVET	APC	10	✓	MTK21-50-355	\$ 92.00
57	CLIP	APC	2	✓	MDFR5-56-145	\$ 4.80
58	FASTENER	APC	3	✓	MGD7A-50-EA1	\$ 9.60
59	PLATE SET FRT	CRU	1	✓	MBCKA-50-7M0A	\$ 210.00
60	SUPPORT PANEL FRT	BR	1	✓	MBCPT-53-100F	\$ 1,021.00
61	PLATE SET LOWER FRT	X nn	1		MBCKC-50-A20B	\$ 117.80
62	STAY LOCK	X nn	1		MBCJH-52-15Y	\$ 44.70
63	UPPER SUPPORT PANEL	DD	1	✓	MBCJH-53-150B	\$ 138.80
64	FRONT FENDER RH	X R	1		MBCJH-52-110	\$ 415.90
65	STAY FENDER RH	X nn	1		MBCJH-52-140	\$ 39.90
66	MUD GUARD FRT RH	X nn	1		MBCJH-56-130E	\$ 185.90
67	FRONT FENDER LH	X R	1		MBCJH-52-210	\$ 415.90
68	STAY FENDER LH	X nn	1		MBCJH-52-240	\$ 43.80
69	MUD GUARD FRT LH	X nn	1		MBCJH-56-140E	\$ 185.90
70	FASTENER	X nn	20		MB45A-56-146A	\$ 60.00
71	HEADLAMP RH	X BR	1	✓	MBCLH-51-030B	\$ 3,655.10
72	BRACKET HEADLAMP RH	X BR	1	✓	MBCKA-50-150A	\$ 56.20
73	HEADLAMP LH	X nn	1		MBCLH-51-040B	\$ 3,655.10
74	BRACKET HEADLAMP LH	X nn	1		MBCKA-50-160A	\$ 56.20
75	CLIP	APC	10	✓	MDFR5-56-145	\$ 24.00
76	HARNES FRONT	X nn	1		MBEWT-67-010D	\$ 6,183.50
77	DUCT, FRESH AIR	CRU	1	✓	MP5E2-13-200A	\$ 94.20
78	CHAMBER RESONANCE	X nn	1		MP5E2-13-195A	\$ 49.80
79	BONNET	DD	1	✓	MBCY0-52-31XD	\$ 1,040.80
80	WEATHERSTRIP, BONNET OUTER	X nn	1		MBCJH-56-770A	\$ 55.90

78	FASTENER	MC		5	✓	MBCJH-56-742	\$ 12.50
79	WEATHERSTRP, BONNET INNER	X nn		1		MBCJH-56-750	\$ 20.60
80	FASTENER	X nn		8		MBC1D-58-762	\$ 27.20
81	COVER, HOLE BONNET	MC		1	✓	MBC1D-56-052	\$ 5.10
82	HINGE RH	X nn		1		MBCJH-52-410	\$ 48.80
83	HINGE LH	X nn		1		MBCJH-52-420	\$ 48.80
84	LOCK, BONNET	DT		1	✓	MBCKT-56-620	\$ 164.40
85	PROTECT, LOCK-BONNET	X nn		1		MBCJH-56-627B	\$ 19.10
86	CONDENSER ASSY	X nn		1		MBDGF-61-480A	\$ 945.90
87	RING, 'O'-NO.1	X nn		1		MGJ6A-61-J19	\$ 11.10
88	RING, 'O'-NO.2	X nn		1		MGJ6E-61-J19	\$ 7.10
89	RADIATOR ASSY	X nn		1		MPAF1-15-200	\$ 998.00
90	FAN ELECTRIC ASSY	X nn		1		MPAF1-15-025A	\$ 1,040.10
91	TANK, SUB-RAD BP/DM	X nn		1		MPAF1-15-351	\$ 55.40
92	BRACKET, SUB TANK	X nn		1		MPAF1-15-371	\$ 20.80
93	REAR BUMPER	BR		1	✓	MBCKA-50-221ABB	\$ 997.40
94	BRACKET CENTE REAR BUMPER	BR		1	✓	MDFR5-50-251	\$ 5.40
95	REINFORCEMENT REAR	DD		1	✓	MBCJH-50-260	\$ 541.70
96	RETAINER LH REAR	BR		1	✓	MBCKA-50-2J1	\$ 33.20
97	RETAINER RH REAR	BR		1	✓	MBCKA-50-2H1	\$ 33.20
98	GROMMET, SCREW	MC		4	✓	MBCKA-50-0Z1	\$ 9.60
99	REFLECTOR LH	X nn		1		MB0J8-51-5M0	\$ 36.00
100	REFLECTOR RH	BR		1	✓	MB0J8-51-5L0	\$ 36.00
101	COVER TOWING LH REAR	MIS		1	✓	MBCKA-50-EL1 BB	\$ 12.80
102	COVER TOWING RH REAR	MIS		1	✓	MBCKA-50-EK1 BB	\$ 12.80
103	CAP, DRIP MOULD	CR4		21	✓	MG52A-50-5A1B2M	\$ 30.40
104	SPLASH SHIELD LH REAR	X nn		1		MBCKA-50-350	\$ 83.50
105	SPLASH SHIELD RH REAR	TAI		1	✓	MBEPN-50-340	\$ 61.90
106	FASTENER	MC		8	✓	MB45A-56-146A	\$ 24.00
107	PLATE SET RR BUMPER	BR		1	✓	MBCKA-50-2C0A	\$ 213.80
108	STAY, RR BUMPER	DD (photo)		1	✓	MBCKA-50-290	\$ 91.90
109	COVER, UNDER-REAR	BR		1	✓	MBCKA-50-C51C	\$ 63.20
110	RETAINER S.S ULTRASONIC	MC		2	✓	MB0J8-67-UC6	\$ 46.80
111	RETAINER S.S ULTRASONIC	MC		1	✓	MB0J5-67-UC5 33	\$ 44.90
112	RETAINER S.S ULTRASONIC	MC		1	✓	MB0J6-67-UC5 PR	\$ 62.20
113	RETAINER S.S ULTRASONIC	MC		1	✓	MB0L8-67-UC5	\$ 25.10
114	RETAINER S.S ULTRASONIC	MC		1	✓	MB0L9-67-UC5	\$ 25.10
115	RETAINER S.S ULTRASONIC	MC		1	✓	MB0M1-67-UC5	\$ 25.10
116	RETAINER S.S ULTRASONIC	MC		1	✓	MB0M2-67-UC5	\$ 25.10
117	SENSOR ULTRASONIC	MIS		2	✓	MB0J8-67-UC1 2M	\$ 1,140.00
118	BRACKET REAR LH BLIND SPOT MONITOR	X nn		1		MBCKA-50-2B1A	\$ 95.40
119	BRACKER REAR RH BLIND SPOT MONITOR	BR		1	✓	MBCKA-50-2A1A	\$ 95.40
120	MONITOR, BLIND SPOT	X nn		2		MB0J9-67-Y30C	\$ 3,601.40
121	TAPE, PROTECTOR	MC		3	✓	MBCKA-50-EM1	\$ 14.10
122	CORD SHORT REAR BUMPER	BR		1	✓	MBDGI-67-A20A	\$ 508.90
123	CAMERA BACK MONITOR	BR		1	✓	MB0J8-67-RC0A	\$ 1,066.80
124	REAR END PANEL	DD (photo)		1	✓	MBCYM-70-752	\$ 691.30

125	TAIL LAMP PANEL RH	4	nn	1	✓	MBCJH-70-440	\$ 166.50
126	TAIL LAMP PANEL LH	1	nn	1		MBCJH-71-440	\$ 166.50
127	REAR FENDER RH	1	nn	1	✓	MBCYA-70-410	\$ 1,643.60
128	REAR FENDER LH	1	nn	1	✓	MBCYA-71-410	\$ 1,643.60
129	REAR FENDER LOWER RH	1	nn	1		MBCJH-70-4A1	\$ 107.60
130	REAR FENDER LOWER LH	1	nn	1		MBCJH-71-4A1	\$ 107.60
131	FLOOR PANEL	1	nn	1	✓	MBCYH-53-70X	\$ 1,244.00
132	SIDE FLOOR LH	1	nn	1		MBCJH-54-731	\$ 69.70
133	SIDE FLOOR RH	1	nn	1		MBCJH-53-731	\$ 69.70
134	BRACKET JACK FLOOR PANEL	1	nn	1		MBCJH-53-76XA	\$ 28.50
135	FRAME RHR UPPER, FLR. PANEL BP	1	nn	1		MBCJH-53-7FXA	\$ 177.00
136	FRAME LHR UPPER BP	1	nn	1		MBCJH-54-7FXA	\$ 177.00
137	PLUG, HOLE FLOOR PANEL	2	nn	2		MBR70-51-264	\$ 4.80
138	PLUG HOLE FLOOR PANEL	2	nn	2		MGHP9-56-056A	\$ 6.40
139	PLUG, DRAIN	2	nn	2		MB45A-56-052	\$ 5.40
140	CHAMBER, EXTRACTOR	2	nn	2		MBCJH-51-920A	\$ 86.20
141	TRUNK LID	1		1	✓	MBCY0-52-61XA	\$ 896.00
142	WEATHERSTRIP TRK LID	1		1	✓	MBCJH-56-95XA	\$ 84.70
143	COVER, HOLE RR LID	3		3	✓	MD24H-62-866	\$ 7.50
144	WEATHERSTRIP TRUNK	1		1	✓	MBCKA-56-951A	\$ 153.20
145	HINGE LH TRUNK LID	1		1	✓	MBCJH-52-720	\$ 175.90
146	HINGE RH TRUNK LID	1		1	✓	MBCJH-52-710	\$ 175.90
147	MOULD, RR WINDOW	1		1	✓	MBCKA-50-611	\$ 49.90
148	SPACER W/SCREEN	2		2	✓	MBCKA-50-897	\$ 23.80
149	SPACER	3		3	✓	MGJ6A-50-897	\$ 38.40
150	PAD SILENCER FLOOR PANEL	2		2	✓	M0208-76-071	\$ 43.60
151	MAT(C) (110X110)	1		1	✓	MBCJH-68-81XA	\$ 658.00
152	SUB TRUNK, ROOM RH	1	nn	1		MBCJH-68-8MYB	\$ 241.70
153	SUB TRUNK, ROOM LH	1	nn	1		MBCJH-68-8MZA	\$ 197.10
154	TRIM END PANEL REAR	1		1	✓	MBCJH-68-89XA	\$ 69.20
155	BEZEL, LOCK	1		1	✓	MBCJH-68-894A	\$ 14.60
156	TRIM(L), TRUNK SIDE	1	nn	1		MBCJH-68-870B	\$ 641.90
157	BRACKET(L), TRUNK SID	1	nn	1		MBCJH-68-8HY	\$ 21.70
158	INSULATOR(L), TRUNK SIDE	1	nn	1		MBCJH-68-8RYA	\$ 100.40
159	TRIM(R), TRUNK SIDE BP	1		1	✓	MBCJH-68-850B	\$ 759.60
160	COVER TRIM, TRUNK SIDE	1		1	✓	MBCJH-68-8T0A	\$ 78.10
161	BRACKET(R), TRUNK SID	1	nn	1		MBCJH-68-8HX	\$ 21.70
162	INSULATOR RH, TRUNK SIDE	1	nn	1		MBCJH-68-8RXA	\$ 118.20
163	TRIM, TRUNK LID	1		1	✓	MBDMA-68-8W1A	\$ 230.10
164	MUD GUARD RH REAR	1	nn	1		MBCJH-56-1H1A	\$ 172.70
165	MUD GUARD LH REAR	1	nn	1		MBCJH-56-1J1B	\$ 172.70
166	INSULATOR, SPARE TIRE	1	nn	1		MDH4G-56-135	\$ 22.60
167	INSULATOR, HEAT	1		1	✓	MBCJH-56-451D	\$ 59.20
168	SILENCER, MAIN	1		1	✓	MPY1C-40-100G	\$ 1,486.80
169	GASKET EXHAUST	1		1	✓	MPE23-40-305	\$ 25.40
170	PIPE, MIDDLE CAT	1		1	✓	MP5L2-40-600A	\$ 1,814.80
171	GASKET EXHAUST	1		1	✓	MP549-40-305	\$ 15.40

172	CLAMP, SPARE TIRE	1	✓	MBCJH-56-960	\$ 26.60
173	WHEEL, DISK-TEMPORARY	1	✓	M9965-51-4060	\$ 370.00
174	LAMP TRUNK LID RH	1	✓	MBCJH-51-3F0B	\$ 523.90
175	LAMP TRUNK LID LH	1	✓	MBCJH-51-3G0B	\$ 523.90
176	GASKET LAMP TRUNK LID	2	✓	MBCJH-51-3H8	\$ 39.60
177	FASTENER	2	✓	MEG21-51-146	\$ 12.40
178	GROMMET, SCREW-R.COMB	6	✓	MGA7B-51-146	\$ 19.80
179	TAIL LAMP RH	1	✓	M80J9-51-150	\$ 903.30
180	TAIL LAMP LH	1	✓	M80J9-51-160	\$ 903.30
181	GROMMET	4	✓	MK123-51-039	\$ 11.20
182	COVER RH TAIL LAMP	1	✓	MBCJH-51-174	\$ 14.60
183	COVER LH TAIL LAMP	1	✓	MBCJH-51-184	\$ 14.60
184	ORNAMENT MAZDA 3	1	✓	MBCJH-51-771A	\$ 42.50
185	ORNAMENT SKYACTIV	1	✓	MBCJH-51-721	\$ 34.60
186	MASCOT, WITH OPEN SWITCH	1	✓	MBCJL-51-730B	\$ 179.20
187	LABEL, CAUTION	1	✓	MPE01-15-031	\$ 3.50
188	LABEL, CAUTION	1	✓	MKF49-61-439	\$ 3.50
189	EMBLEM M-HYBRID	1	✓	M11-M-HYBRID	\$ 36.70
190	COOLANT LONG LIVE 4 LTS	1	✓	M11-NAC9-15-004MM	\$ 54.80

TOTAL PARTS \$ 62,786.62

TOTAL PARTS COST \$ 62,786.62

SUPPLEMENTARY

NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1							
2							
3							
TOTAL PARTS							\$ -
TOTAL PARTS COST							\$ -

Labour Description

		REVISED	PRICES
1	TO REPLACE FRONT BUMPER, FRONT FENDER LH & RH AND BONNET. 2.5 x 660	1650	\$ 3,300.00
2	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR FENDER LH & RH, REAR FENDER LOWER PANEL LH & RH, REAR END PANEL, TAIL LAMP PANEL LH & RH, SIDE FLOOR PANEL LH & RH AND FLOOR PANEL. 17 x 660	8580	\$ 9,900.00
3	TO RESPRAY FRONT BUMPER, FRONT FENDER LH & RH AND BONNET. 4 x 630	2520	\$ 3,150.00
4	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR FENDER LH & RH, REAR FENDER LOWER PANEL LH & RH, REAR END PANEL, TAIL LAMP PANEL LH & RH, SIDE FLOOR PANEL LH & RH AND FLOOR PANEL. 6 x 630	3880	\$ 7,560.00
5	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING x 2 180 x 4	770	\$ 1,260.00

6		TO REMOVE AND REFIT CARPET AND SEATS FOR ACCESS.		\$ 660.00
7	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST. (phib)	NETT	\$ 560.00
8	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	NETT	\$ 120.00
9	MZ-BR-PANEL1	TO REMOVE & INSTALL RADIATOR, RADIATOR FAN AND FRONT SUPPORT PANEL. TO CONDUCT PRESSURE TEST & PERFORM LEAK TEST.		\$ 660.00
10	MZ-BR-TOP-UP	TO REMOVE & INSTALL CONDENSOR, AIR COND PIPE AND TOP-UP GAS COOLING SYSTEM.		\$ 330.00
11	MZ-BR-HARNES	TO REMOVE & REPLACE THE WIRE HARNESS ASSY. 660	X ?	\$ 990.00
12	MZ-BR-CROSS2	TO REMOVE & INSTALL CROSSMEMBER ASSY FOR ACCESS. (phib)	X ?	\$ 660.00
13	MZ-BR-CHASIS	TO REALIGN BODY CHASSIS ALIGNMENT.	X ?	\$ 660.00
14	MZ-BR-FUELTK	TO REMOVE & INSTALL FUEL TANK FOR ACCESS. (phib)	X ?	\$ 990.00
15	MZ-BR-EXASSY	TO REMOVE & INSTALL REAR EXHAUST ASSY.		\$ 660.00
16	MZ-BR-WHEAL	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	X ⁿ NETT	\$ 560.00
17	MZ-BR-FRTSEN	TO TRANSFER FRONT PEDESTRIAN SENSORS.	330	\$ 660.00
18	MZ-BR-REVSSEN	TO TRANSFER REVERSE SENSORS.	330	\$ 660.00
19	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	330	\$ 660.00
20		TO SUPPLY NUMBER PLATE x2	NETT	\$ 140.00
21		TO CALIBRATE SAFETY DISTANCE MODULE.	X ⁿ ? NETT	\$ 560.00
22		TO CALIBRATE FRONT SENSOR RADAR.	X ⁿ ? NETT	\$ 560.00
23		TO MOUNT CAR ON CAR O LINER AND REALIGN THE CAR BODY ACCORDING MAZDA SPECIFICATION. (phib)	X ⁿ ? NETT	\$ 1,500.00
24	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	200	\$ 250.00
25	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	250	\$ 300.00
26	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION. (INCLUDING NEW PARTS AND CAOUTCHOU)	400	\$ 800.00

27	MZ-BR-SUNDRI	SUNDRIES.	30	\$ 100.00																					
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.			<table border="1"> <tr><td>TOTAL LABOUR</td><td>\$ -</td><td>\$ 38,210.00</td></tr> <tr><td>TOTAL PARTS</td><td>\$ -</td><td>\$ 62,786.62</td></tr> <tr><td>TOTAL</td><td>\$ -</td><td>\$ 100,996.62</td></tr> <tr><td>LESS EXCESS</td><td>\$ -</td><td>\$ -</td></tr> <tr><td>TOTAL AFTER EXCESS</td><td>\$ -</td><td>\$ 100,996.62</td></tr> <tr><td>GST 7%</td><td>\$ -</td><td>\$ 7,069.76</td></tr> <tr><td>GRAND TOTAL</td><td>\$ -</td><td>\$ 108,066.38</td></tr> </table>		TOTAL LABOUR	\$ -	\$ 38,210.00	TOTAL PARTS	\$ -	\$ 62,786.62	TOTAL	\$ -	\$ 100,996.62	LESS EXCESS	\$ -	\$ -	TOTAL AFTER EXCESS	\$ -	\$ 100,996.62	GST 7%	\$ -	\$ 7,069.76	GRAND TOTAL	\$ -	\$ 108,066.38
TOTAL LABOUR	\$ -	\$ 38,210.00																							
TOTAL PARTS	\$ -	\$ 62,786.62																							
TOTAL	\$ -	\$ 100,996.62																							
LESS EXCESS	\$ -	\$ -																							
TOTAL AFTER EXCESS	\$ -	\$ 100,996.62																							
GST 7%	\$ -	\$ 7,069.76																							
GRAND TOTAL	\$ -	\$ 108,066.38																							
SUPPLEMENTARY LABOUR DESCRIPTION																									
			REVISED	PRICES																					
1		#N/A																							
2		#N/A																							
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.			<table border="1"> <tr><td>TOTAL LABOUR</td><td>\$ -</td><td>\$ -</td></tr> <tr><td>TOTAL PARTS</td><td>\$ -</td><td>\$ -</td></tr> <tr><td>TOTAL</td><td>\$ -</td><td>\$ -</td></tr> <tr><td>LESS EXCESS</td><td>\$ -</td><td>\$ -</td></tr> <tr><td>TOTAL AFTER EXCESS</td><td>\$ -</td><td>\$ -</td></tr> <tr><td>GST 7%</td><td>\$ -</td><td>\$ -</td></tr> <tr><td>GRAND TOTAL</td><td>\$ -</td><td>\$ -</td></tr> </table>		TOTAL LABOUR	\$ -	\$ -	TOTAL PARTS	\$ -	\$ -	TOTAL	\$ -	\$ -	LESS EXCESS	\$ -	\$ -	TOTAL AFTER EXCESS	\$ -	\$ -	GST 7%	\$ -	\$ -	GRAND TOTAL	\$ -	\$ -
TOTAL LABOUR	\$ -	\$ -																							
TOTAL PARTS	\$ -	\$ -																							
TOTAL	\$ -	\$ -																							
LESS EXCESS	\$ -	\$ -																							
TOTAL AFTER EXCESS	\$ -	\$ -																							
GST 7%	\$ -	\$ -																							
GRAND TOTAL	\$ -	\$ -																							

Steve (LKK)
 15/10/21, 10.44am
 ML PL
 P/P
 R BL M
 26 days

TRANS EUROKARS PTE LTD

 Authorised Signature.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "visual" or "estimated" basis
 - No illegal modification(s) is/are
 - Supplementary item(s) must be approved and is subject to final approval from the Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

313Z

Vehicle Details

Vehicle No.:

SMZ4388P

Vehicle to be Exported:

No

Intended Deregistration Date:

12 Oct 2021

Vehicle Make:

MAZDA

Vehicle Model:

MAZDA3 4DR 1.5 AT M-HYBRID ASTINA

Primary Colour:

Grey

Manufacturing Year:

2021

Engine No.:

P520724503

Chassis No.:

JM6BP2SAAM1106878

Maximum Power Output:

88.0 kW (118 bhp)

Open Market Value:

\$25,571.00

Original Registration Date:

27 Apr 2021

First Registration Date:

27 Apr 2021

Transfer Count:

0

Actual ARF Paid:

\$12,800.00

Intended PARF Rebate Details

Yes

PARF Eligibility:

26 Apr 2031

PARF Eligibility Expiry Date:

\$9,600.00

PARF Rebate Amount:

26 Apr 2031

Intended COE Rebate Details

A - Car up to 1600cc & 97kW (130bhp)

COE Expiry Date:

10

COE Category:

\$45,600.00

COE Period(Years):

\$43,497.00

QP Paid:

\$53,097.00

COE Rebate Amount:

Total Rebate Amount:

The information contained herein is correct as at 12 Oct 2021

OK

(RED \$52,996.



10 YEAR ANNIVERSARY SALE



\$5,000 DISCOUNT ON ALL MODELS

[Get offer](#)



Min Price to No Max

Depreciation

Vehicle Type

Category

Search

Advanced Search



Free upgrade to guaranteed COE.

For your peace of mind.

30% downpayment available for Mazda6 Standard

Limited units only.

Life's Ride.





[LEARN MORE](#)

Mazda (Authorised Distributor)
Trans Eurokars (Mazda)
Hotline : 66036118 / 63958888

07-Oct Pricelist [Select Date](#)

Mazda (Parallel Importer)
Some models are only sold by parallel importers.
View only parallel imported Mazda



New Mazda Cars for Sale (11 vehicles)

Sort by Most Popular

15 results/page

Car Model

Price

Dealer

Built in

User Rating

Mazda 3 Sedan Mild Hybrid



1.5 Classic (A)

1.5 Elegance (A)

1.5 Astina (A)

Promotion available

\$98,888

\$9,600 /yr ?

\$103,888

\$9,900 /yr ?

\$110,888

\$10,500 /yr ?

• 18.1km/l | 118bhp | 6-speed (A)

• 18.1km/l | 118bhp | 6-speed (A)

• 18.1km/l | 118bhp | 6-speed (A)

Trans Eurokars (Mazda)

Japan

16 User Reviews

Mazda 6 Sedan



2.0 Standard (A)

2.0 Executive (A)

(RED \$52,996.62; Promotion available)

\$127,888

\$11,800 /yr ?

\$135,888

\$12,400 /yr ?

• 14.7km/l | 163bhp | 6-speed (A) SKYACTIV-DRIVE

• 14.7km/l | 163bhp | 6-speed (A) SKYACTIV-DRIVE

Trans Eurokars (Mazda)

Japan

22 User Reviews

Mazda CX-8 - Available in 6-or 7-seater. Now from \$176,888. Free upgrade to guaranteed COE for limited units.

Mazda CX-30 - Limited demo units available from \$129,888 - Best Crossover of the Year 2020 awarded by sgCarMart.

PROMOTION
[View All](#)

Mazda CX-30



2.0 Classic (A)

2.0 Elegance (A)

2.0 Luxury (A)

Promotion available

\$134,888

\$12,300 /yr ?

\$142,888

\$13,300 /yr ?

\$147,888

\$13,500 /yr ?

• 15.2km/l | 162bhp | 6-speed (A)

• 15.2km/l | 162bhp | 6-speed (A)

• 15.2km/l | 162bhp | 6-speed (A)

Trans Eurokars (Mazda)

Japan

5 User Reviews

sgCarMart Crossover of the Year



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	12/10/2021 11:45 (SGT)
Date of Accident	10/10/2021 17:15 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	CTE(AYE) BEFORE PIE(CHANGI) EXIT, LANE 2
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMZ4388P
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ZHANG CHUANDA
NRIC No	S9775313Z
Email Address	fatboy521@gmail.com
Mobile Phone No	(Phone) +65-92275958
Alternative Phone No	+65-92275958

VEHICLE PARTICULARS

Manufacturer	Mazda
Model	3
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1500

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5121878541
Cover Note Number	-

DRIVER

Name of Driver	ZHANG CHUANDA
NRIC No	S9775313Z

Date Of Birth
Occupation
Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode

20/01/1997
Indoor
20/04/2021
6 MONTHS
Male
(Phone) +65-92275958
+65-92275958
fatboy521@gmail.com
BLK 442 #02-117 CLEMENTI AVENUE 3

Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

120442
Yes
No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Chain Collision
Raining
Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other vehicle or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?

No
3
Yes
No
Yes
1
Yes

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Police Station Name
Police Station Phone No
Alt. Police Station Phone No
Police Station Address
Was notice of intended Prosecution given?
If yes, against whom?

Yes
Kampong Java Neighbourhood Police Centre
(Phone) +65-1800295999
(Fax) +65-63913442
21 Kampong Java Road Singapore 228892
No

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT FOR STATEMENT

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Reasons for not uploading a video of the accident
Was there any audio recorded?

Yes
Yes
ADV OI TO SEND VIDEO TO MOTORVIDEO@INCOME.COM.SG
No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour

SLV8551R

Vehicle Category	Private car
Name of Driver	ONG WOEI HSIUNG
NRIC No	S8213844G
Contact Number	(Phone) +65-82224048
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	3

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHB5021B
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	YIP SENG FATT NEWTON
NRIC No	S1646125C
Contact Number	(Phone) +65-90664510
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	3

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	ZHANG CHUANDA
Gender	Male
Phone No	(Phone) +65-92275958
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	24
Injuries Sustained	MEDICAL LEAVE FROM 10/10/2021 TO 12/10/2021 SUFFERED INJURIES TO LEFT UPPER CHEST SMZ4388P
Injured person in which vehicle?	No
Were seat belts worn?	No
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 12/10/2021
1115HRS

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: SUMAN SUKUMAR
NIC/FIN No: S990983

SKETCH PLAN



A : SMZ4388P

B : SLV8551R

C : SHB5021B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT FOR STATEMENT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time: 12/10/2021

1115HAS

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

NAME: **SUMAN SUKUMAR**

INCL/IN No: S990565



**SINGAPORE
POLICE FORCE**



E/20211012/7011

1 of 2

POLICE REPORT (NP299)

Police Station Of Origin
Tanglin Division HQ
21 Kampong Java Road SINGAPORE
228892
Tel No: 1800-3910000

Report No. E/20211012/7011

Date/Time Report Made 12/10/2021 11:10	Video Report No.		Station Diary No.	
Name Of Informant ZHANG CHUAN DA	Address 442 CLEMENTI AVENUE 3 #02-117 SINGAPORE 120442			
ID Type / ID No. NRIC NO / S9775313Z	Contact No. Home/Office:		Mobile: 92275958	
Nationality SINGAPORE CITIZEN	Email Address FATBOYY521@GMAIL.COM			
Occupation SELF EMPLOYED	Sex Male	Age 24	Date of Birth 20/01/1997	Race Chinese
Institution/School Name	Language English			
Date/Time Of Incident 10/10/2021 17:15 - 10/10/2021 19:00	Location Of Incident PIE TO MACPHERSON			

Brief details.

My car slow down and brake, felt a strong impact from the back and pushes my car forward and hit onto the front car rear portion , came out and check after impact, found out it was a chain collision, went to consult doctor after accident as felt pain from my chest, given 3 days Mc.

Subjects Involved	
Victim	
Person Name	ZHANG CHUAN DA

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:
The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:
12/10/2021 11:10

Classification Of Case:



**SINGAPORE
POLICE FORCE**



E/20211012/7011

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20211012/7011

ID Type	NRIC NO	ID No	S9775313Z
Gender	Male	Age	24
Race	Chinese	Language	English
Occupation	SELF EMPLOYED	Address	442 CLEMENTI AVENUE 3 #02-117 SINGAPORE 120442
Mobile No	92275958	Is Informant A Victim?	Yes
Person Name	ZHANG CHUANDA (Informant)		

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:

The identity of the person making this
report has been authenticated by Singpass.
No signature is required.

Date/Time:
12/10/2021 11:10

Classification Of Case: