

Hui Zhen (LKK Auto)

From: Simon Ho (LKKAuto)
Sent: Friday, 22 October 2021 1:55 PM
To: Hui Zhen (LKK Auto)
Subject: RE: SMZ 4388P Surveyed by Steve (CS/SMR21010590/Euf3)

Dear Hui Zhen,

Audit check done for SMZ4388P without problem as repairer can undertake repair limit at S\$48,000.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Hui Zhen (LKK Auto)
Sent: Friday, 22 October, 2021 1:17 PM
To: Simon Ho (LKKAuto)
Subject: RE: SMZ 4388P Surveyed by Steve (CS/SMR21010590/Euf3)

Dear Simon,

For your reaudit.

Repairer will undertake repair limit at \$ 48,000.

Steve revised MV to \$102K

Best Regards,

Hui Zhen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: huizhen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon Ho (LKKAuto)
Sent: Friday, 15 October 2021 2:44 PM

To: Hui Zhen (LKK Auto)

Subject: RE: SMZ 4388P Surveyed by Steve (CS/SMR21010590/Euf3)

Dear Hui Zhen,

Audit check done for SMZ4388P, found uneconomical to repair.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Hui Zhen (LKK Auto)

Sent: Friday, 15 October, 2021 2:29 PM

To: Simon Ho (LKKAuto)

Subject: SMZ 4388P Surveyed by Steve (CS/SMR21010590/Euf3)

Dear Simon,

For your audit.

Workshop not confirm total loss or repair.

Best Regards,

Hui Zhen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: huizhen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)