Asher Sng (LKKAuto)

From: Mei Kwan (LKKAuto)

Sent:Friday, 17 December 2021 19:18To:chan pick yuen; Asher Sng (LKKAuto)Cc:Hsiao Tong (LKKAuto); Admin A

 Subject:
 RE: SMQ9442E & SGW3055T DOA 9.10.21 *** LKK REF : CC6/CTI21010595/Aea3

 Attachments:
 Full_accident_report_8118753_11-10-2021_145319 PW_ SMQ9442E5507J.PDF;

INVOICE.PDF; LTA FEE.PDF; LOA.PNG; PHOTO-2021-10-12-10-20-14.jpg;

PHOTO-2021-10-12-10-20-12.jpg

Follow Up Flag: Follow up Flag Status: Flagged

From: chan pick yuen [mailto:chris_chanbebe@hotmail.com]

Sent: Friday, December 17, 2021 6:08 PM
To: Admin A admin-a@lkkauto.com

Cc: Hsiao Tong (LKKAuto) < chewht@lkkauto.com > Subject: Fwd: SMQ9442E & SGW3055T DOA 9.10.21

Dear Sir / Mdm,

Your refer: SGW3055T -China taiping Our GIA report password: SMQ9442E5507J

Enclosed is our client's GIA, LOA, LTA fee & invoice.

As request following:

RC \$8200.00 -As agreed

loss of use \$1320.00 (\$120 -2800cc X 11 Days -9 Days recommend + 1 day waiting PRS + 1 days weekend - total 11 days)

LTA \$7.45

@ 100% (direct from behind with scene photos)

Total \$ 9527.45

Please let us have your offer & reply soon . Thanks

Best Regards

Chris Chan SIN FATT DIESEL MOTOR

HP: 92712214



Virus-free. www.avg.com

LETTER OF AUTHORISATION

SIN-FATT DIESEL MOTOR BLOCK 3020A UBI ROAD 1 # 01-33 # 05-441 SINGAPORE 408714

Date: _

Accident on	2 00 . 20st T
Dear Sir; 9/10/21@ 1345hr_ Accident on SMQ 9442E	8 54W 3035 1
Alone CTE Serangoon	
	SMQ 9442E
I /We:the registered owner /driver of vehicle registration no: have involved in the above accident. I/We hereby authorize M/S SIN FATT DIESEL MOTOR forthwith.	
matter. And if applicable, my/our solicitors shall accept this as my the amount as deemed compensated direct to you after deduction client basis.	ny/our irrevocable authority to pay on of their costs on a Solicitor and
I/We undertake to co-operate fully with you and our solicitors to	o ensure that claim is successiui.
I/We also authorize you to sign all discharge vouchers/indemnit relation with the above claim in my/our absence.	ry forms and all necessary papers in
Your kind co-operation in this matter will be much appreciated.	4
Thank you.	
Thank you. Yours truly.	
Yours truly.	
Yours truly.	

SIN FATT DIESEL MOTOR

Blk 3020A #01-33 Ubi Road 1 Singapore 408714 Business Reg.No: 377435/00K

Date: 17th DEC 21

INVOICE

NG KOK CHUAN Blk 3020A #01-33 Ubi Road 1 Singapore 408714

Accident date:09th OCT 2021

Final Bill For Vehicle No: SMQ9442E TOYOTA ALPHARD

Descriptions		AMOUNT
Lump Sum repair cost as recommended by LKK AUTO CONSULTANTS PTE LTD		\$8,200.00
	Total	\$8,200.00

S/ DLRS: EIGHT THOUSAND TWO HUNDRED ONLY



Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time: 11 Oct 2021 / 16:06:20

Receipt Date/Time: 11 Oct 2021 / 16:06:19

Tax Invoice/Receipt

Receipt No.: ITNET-00000-211011-002780

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SGW3055T As at 09 Oct 2021/13:45:00 Insurance Co: CHINA TAIPING INSURANCE (\$ 1 Insurance Enquiry - SGW3055T	SINGAPORE) PTE LTD			
Enquiry Fee 20211011160506890293		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	20211011160533287	Direct Debit: eNETS Debit (Internet Banking)		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.