

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Not Authorized
dhr
14/10/21
2/5#11,000/
12 days

VEHICLE No: SLJ 6706M

1PC	FRONT DOOR O/S	Boddy	1091.70	\$1,415.00
1PC	FRONT DOOR OUTER HANDLE O/S	twi	192.00	\$282.00
1PC	FRONT DOOR INNER LOCK O/S	shuts/jm	285.00	\$453.00
1PC	FRONT DOOR INNER RUBBER O/S	To	145.00	\$166.00
1PC	FRONT DOOR INNER TRIM O/S	de/to	641.00	\$688.10
2PCS	FRONT DOOR HINGES O/S @ \$90.00	11		\$180.00 X
1PC	FRONT DOOR CHECKER O/S	11		\$121.00 X
1PC	FRONT DOOR GLASS OUTER MOULDING O/S	twi	103.50	\$165.00
1PC	FRONT DOOR GLASS O/S	11		\$255.10 X
1PC	FRONT DOOR GLASS REGULATOR & MOTOR O/S	sent/jm	420.00	\$455.30
1PC	FRONT DOOR SPEAKER O/S	11		\$250.00 X
1PC	CENTRE PILLAR O/S	Boddy	688.00	\$988.20
1PC	CENTRE PILLAR INNER GARNISH O/S	twi	180.30	\$185.20
1PC	ROCKER PANEL O/S	Boddy	1209.70	\$1,299.10
1PC	REAR DOOR O/S	11	1099.00	\$1,399.10
1PC	REAR DOOR OUTER HANDLE O/S	twi	192.00	\$245.00
1PC	REAR DOOR INNER RUBBER O/S	To	145.00	\$182.00
1PC	REAR DOOR INNER TRIM BOARD O/S	de/to	550	\$600.50
2PCS	REAR DOOR HINGES O/S @ \$90.00	sent		\$180.00
1PC	REAR DOOR CHECKER O/S	twi		\$121.00
1PC	REAR DOOR GLASS OUTER MOULDING O/S	twi		\$108.90
1PC	REAR DOOR GLASS O/S	11		\$255.00 X
1PC	REAR DOOR GLASS REGULATOR & MOTOR O/S	sent/jm	405	\$455.00
1PC	REAR DOOR SPEAKER O/S	11	225	\$250.00
1PC	REAR DOOR INNER STEP GARNISH O/S	To	115	\$182.00
1PC	REAR DOOR INNER HANDLE BRACKET O/S	11	188	\$205.00
1PC	REAR DOOR INNER CHANNEL RUBBER O/S	twi		\$285.00
1PC	REAR FENDER O/S	Boddy/jm	1806.70	\$1,915.00
1PC	REAR FENDER INNER TRIM O/S	11		\$242.00 X
1PC	REAR FENDER QUARTER GLASS O/S	11	288.00	\$305.00
1PC	REAR WINDSCREEN MOULDING	11	85.60	\$110.00
1PC	REAR BUMPER	11		\$482.00 X
1PC	REAR SHOCK ABSORBER O/S	twi	277.50	\$322.00
1PC	REAR TRAILING ARM O/S	sent/jm	455.00	\$665.00
1PC	REAR KNUCKLE ARM O/S	sent	322.00	\$545.00
1PC	REAR KNUCKLE ARM BEARING O/S	dyed		\$225.00
1PC	REAR LOWER ARM O/S	sent	285.00	\$319.00
1PC	REAR LINKAGE O/S	twi		\$68.00
1PC	REAR WHEEL HOUSING PANEL O/S	R		\$945.10 X
				\$17,514.60

2021

123829

S.NETT

1PC	REAR SPORT RIM O/S	cut	\$600.00	350
1PC	REAR TYRE O/S	822	\$200.00	X
1PC	REAR DOOR VISOR O/S	111	\$60.00	50
1SET	REAR DOOR INNER TRIM BOARD CLIPS O/S	111	\$50.00	✓
1PC	REAR WINDSCREEN INNER SEAL	111	\$50.00	40
1PC	REAR WINDSCREEN SEALANT	111	\$50.00	40
1PC	REAR FENDER QUARTER GLASS SEALANT O/S	111	\$50.00	40
1PC	FRONT DOOR VISOR O/S	111	\$60.00	50
1SET	FRONT DOOR INNER TRIM BOARD CLIPS O/S	111	\$50.00	✓

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$80.00	40
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REPLACED REAR FENDER QUARTER GLASS O/S	\$100.00	50
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	\$200.00	120
TO CONDUCT WHEEL ALIGNMENT	\$120.00	60
TO DISMANTLE & REFIX FUEL TANK	111 \$100.00	X
TO RESET & REPROGRAMME SYSTEM	111 \$180.00	X
TO MOUNT VEHICLE ON CAR O-LINER	111 \$380.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$2,800.00	1600
TO PUTTY & SPRAY PAINTING	\$2,500.00	1100
TOTAL	\$25,464.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1238290
P-990632
S.N-670
L-3190
1376632
11013.