



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL	INV No.	AC2107433
50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER	INV Date	28/10/2021
SINGAPORE 048623	Reference	CS3/SMO21010641/Kvf3e2
	Code	SMO

PROFESSIONAL SERVICE FEE

Vehicle No.	FBP 7839T
Insured Veh.	GBF 5806D
Claim No.	CMTD2103065/THE
Policy No.	
Accident Date	09/10/2021
Inspection Date	20/10/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Subtotal	100.00
GST (7%)	7.00
Grand Total	107.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM