

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLA639K Toyota Wish

| No | Qty | Parts Description | Estimated Parts Price |
|---------------------------|-----|--|---------------------------------|
| 1 | 1 | Front right door panel ✓ | \$ 1,465.20 <i>ht - 1292.30</i> |
| 2 | 1 | Rear bumper assy ✗ | \$ 859.20 <i>X</i> |
| 3 | 1 | Rear bumper right retainer ✗ | \$ 44.30 <i>X</i> |
| 4 | 1 | Rear bumper right bracket ✗ | \$ 43.10 <i>X</i> |
| 5 | 1 | Rear right taillamp ✗ | \$ 440.50 <i>X</i> |
| 6 | 1 | Rear right door panel ✓ | \$ 1,261.40 <i>ht -</i> |
| 7 | 1 | Rear right door regulator with motor ✓ | \$ 493.50 <i>ht - 228.70</i> |
| 8 | 1 | Rear right door weatherstrip ✓ | \$ 182.60 <i>cut -</i> |
| 9 | 1 | Rear right door outer handle ✓ | \$ 127.20 <i>cut -</i> |
| 10 | 1 | Rear right door lock mechanism ? | \$ 225.80 <i>ht -</i> |
| 11 | 1 | Rear right door checker linkage ? | \$ 121.30 <i>X nn</i> |
| 12 | 1 | Rear right door inner board ? | \$ 478.20 <i>cut -</i> |
| 13 | 2 | Rear right door hinges ? | \$ 120.10 <i>ht -</i> |
| 14 | 1 | Rear right door glass assy ✓ | \$ 388.80 <i>bn -</i> |
| 15 | 1 | Rear right door glass outer moulding ✓ | \$ 161.40 <i>de - 146.20</i> |
| 16 | 1 | Rear right suspension assy ✗ | \$ 860.60 <i>X</i> |
| 17 | 1 | Rear right wheel hub bearing ✗ | \$ 272.30 <i>X nn</i> |
| 18 | 1 | Rear axle beam ✗ | \$ 1,800.10 <i>X</i> |
| 19 | 1 | Rear right fender ✓ | \$ 1,482.30 <i>ht - 977.40</i> |
| 20 | 1 | Rear right fender inner cowling ✗ | \$ 128.70 <i>X nn</i> |
| 21 | 1 | Rear right quarter glass moulding ✓ | \$ 128.90 <i>X nn -</i> |
| 22 | 1 | Rear windscreen glass moulding ✓ | \$ 280.20 <i>X nn</i> |
| 23 | 1 | Rear right 'B' pillar | \$ 1,859.10 <i>RM</i> |
| | | | <hr/> |
| | | | \$ 13,224.80 |
| less 25% | | | \$ 3,306.20 |
| | | | <hr/> |
| | | | \$ 9,918.60 |
| <u>Special Nett Items</u> | | | |
| 1 | 10 | Rear bumper clips | \$ 60.00 <i>30</i> |
| 2 | 1 | Rear no plate with garnish | \$ 100.00 <i>X nn</i> |
| 3 | 1 | Rear right fender sealant | \$ 100.00 <i>40 over</i> |
| 4 | 1 | Rear windscreen glass sealant | \$ 100.00 <i>X</i> |
| 5 | 1 | Rear right wheel rim | \$ 750.00 <i>X</i> |
| 6 | 1 | Rear right tyre | \$ 300.00 <i>X</i> |
| 7 | 1 | Rear right quarter glass sealant | \$ 80.00 <i>40 over</i> |
| 8 | 1 | Rear right side skirting | \$ 1,400.00 <i>cut - 400</i> |
| 9 | 1 | Rear right side skirting sealant | \$ 100.00 <i>X nn</i> |
| 10 | 10 | Rear right side skirting clips | \$ 60.00 <i>20 over</i> |
| 11 | 6 | Rear right fender inner cowling clips | \$ 40.00 <i>X nn</i> |
| 12 | 8 | Rear right door inner board clips | \$ 45.00 <i>20 over</i> |
| | | | <hr/> |
| | | | \$ 3,135.00 |
| Total parts | | | \$ 13,053.60 |

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLA639K Toyota Wish

| No | Description | Labour Charges |
|-----------------------|--|----------------------------------|
| 1 | Labour for panel beating, cut, weld, straighten rear right affected area and replace rear right damaged parts. | \$ 1,400.00 900 |
| 2 | To putty and spray painting rear right portion. | \$ 1,400.00 900 |
| 3 | To check rear lighting and wiring. | \$ 50.00 X un |
| 4 | To remove and install rear inner garnish and trim to facilitate the repair. | \$ 140.00 X un |
| 5 | To apply anti rust proofing to rear right affected area. | \$ 140.00 40 |
| 6 | To remove and install rear windscreen glass to facilitate the repair. | \$ 140.00 X } |
| 7 | To remove and install rear right undercarriage parts. | \$ 350.00 X } |
| 8 | To balance rear right wheel. | \$ 50.00 X } |
| 9 | To conduct wheel alignment. | \$ 120.00 X } |
| 10 | To remove and install rear right door lock mechanism. | \$ 80.00 60 |
| 11 | To check front right and rear right door central locking for function. | \$ 80.00 30 |
| 12 | To transfer front right door glass to new door. | \$ 80.00 X un |
| 13 | To transfer rear right door glass to new door. | \$ 80.00 X un |
| 14 | To remove and install rear right door regulator with motor assy. | \$ 80.00 60 |
| 15 | To remove and install rear right quarter glass. | \$ 80.00 40 |
| 16 | Towing service. | \$ 100.00 60 ? towing |
| Total labour : | | \$ 4,370.00 un |

1220

Total parts : \$ 13,053.60

Total labour : \$ 4,370.00

Total repair cost : \$ 17,423.60

Tanphi 97495749
 18/10/21 @ 350 pm

US Resurvey after repair
 tanphi@lkkauto.com
 07 days

4168.20
 550
 1220
 5938.20
 4584750
 07 days
 #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: