

ASS. REC. BY:

REF:

AIG/21010697/Kg


Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Cheng Hoo
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 03 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SUX 4099X Yr Regn: 11, 09
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____

Make: Honda Civic c.c. 1595
 Colour: M.P. White A/C: Insured / Std / NI / NA
 Sp. Reading: 137862 T/Radio: Insured / Std / NI / NA
 Eng/No: _____

C/No: JHMFD 462095200684

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: NI / SR/Im / STD A/Rim or _____

Tyre Size: F: 225/45ZR17
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front: R/Bal. 7 mm L/Bal. 7 mm
 Rear: R/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 1/10/21 D.O.I. 19/10/2021

Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Report Format :
 Lump Sum / I.B.I: (\$ _____)

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
Transportation: _____
S - RS - SI _____
Fees _____
Others _____
TOTAL _____

Cheng Hoe Motor Pte Ltd

BK 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLX4099X

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Not Attached

WS Ref:

TP/AIG

Claim Type:

Third Party

Accident Date:

01/10/2021

TP Veh Reg No:

SLP9676P

*11 Rep &
 Recovery After Paint
 3 days*

Estimate No: ES2191001/WS

Date: 19 Oct 2021

Policy No: 5118608928

Veh Reg No: SLX4099X

Make/Model: HONDA HONDA CIVIC
 1.6L 5AT

Chassis No: JHMFD46209S200684

Engine No: R16A14002698

Reg. Date: 02/11/2009

Estimate Repair Cost to Vehicle No :SLX4099X

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 REAR BUMPER	730.20	1 PC	<i>Br</i> 730.20	—
2 REAR BUMPER RH RETAINER	24.30	1 PC	<i>DIY</i> 24.30	✓
3 TAILLAMP RH	308.70	1 PC	<i>CM</i> 308.70	✓
4 REAR BOOT LOGO	25.70	1 PC	<i>me</i> 25.70	✓
			1,088.90	
		Less 20%	217.78	871.12
Special Net				
5 REAR BOOT EMBLEM (MUGEN)	45.00	1 PC	<i>me</i> 45.00	✓
6 REVERSE SENSOR	200.00	1 SET	<i>Shan</i> 200.00	✓
			245.00	245.00
Labour				
7 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, TO KNOCK & REPAIR REAR PANEL, REAR BOOT, REAR RH FENDER & REALIGN THE SAME	500.00	1 LA	500.00	<i>350</i>
8 PUTTY & RESPRAY ON REAR PANEL, BOOT, REAR BUMPER, REAR RH FENDER	700.00	1 LA	700.00	<i>600</i>
			1,200.00	1,200.00
			Total	S\$ 2,316.12
			Add GST @ 7%	162.13
			Total Amount Payable	S\$ 2,478.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey : on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 02/10/2021 16:00 (SGT)
Date of Accident 01/10/2021 21:25 (SGT)
Exact Location of Accident Singapore
Additional Location Information NICOLL HIGHWAY
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLX4099X

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner LIN YIQIANG, IVAN
NRIC No SXXXX867H
Email Address ivanlinyq@gmail.com
Mobile Phone No (Phone) +65-81612200
Alternative Phone No +65-81612200

VEHICLE PARTICULARS

Manufacturer Honda
Model CIVIC 1.6L 5AT
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1595

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5118608928
Cover Note Number 22/08/2020 -01/11/2021

DRIVER

Name of Driver LIN YIQIANG, IVAN
NRIC No SXXXX867H

