

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN CHENG KIAT
43 CHUAN GARDEN

SINGAPORE 558560

ATTN:

Your Ref No: SKT3686R
Claim Type: Third Party
Accident Date: 17/10/2021
TP Veh Reg No: YP8371X

Estimate No: MC1902224
Date: 19 Oct 2021
Policy No: MT/00642749/02
Veh Reg No: SKT3686R
Make/Model: HONDA CITY 1.5 SV
CVT

Estimate Repair Cost to Vehicle No :SKT3686R

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BOOT	1 PC	502.90	
2 REAR BOOT HINGE LH & RH	2 PC	159.60	
3 REAR BOOT EMBLEM	1 PC	21.90	
4 REAR BOOT CITY LOGO	1 PC	21.50	
5 REAR BOOT IVTEC	1 PC	21.90	
6 REAR BOOT CHROME MOULDING	1 PC	98.50	
7 REAR BOOT NO PLATE LAMP LH & RH	2 PC	76.80	
8 REAR BOOT REVERSE CAMERA	1 PC	625.90	
9 REAR BOOT OUTER SWITCH - CHECK PRICE	1 PC	0.00	
10 REAR BOOT INNER LOCK	1 PC	105.70	
11 REAR BOOT INNER LOCK STRIKER	1 PC	25.40	
12 REAR BOOT RUBBER	1 PC	84.20	
13 REAR BOOT INNER TRIM	1 PC	99.70	
14 REAR BOOT INNER TRIM CLIPS	10 PC	55.00	
15 REAR BOOT STOPPER ROUND	2 PC	19.40	
16 REAR BOOT STOPPER RECTANGLE - CHECK PRICE	2 PC	0.00	
17 REAR BOOT LAMP LH & RH	2 PC	194.40	
18 TAILAMP LH & RH	2 PC	450.80	
19 TAILAMP PANEL LH & RH	2 PC	196.40	
20 REAR BUMPER	1 PC	463.70	
21 REAR BUMPER SIDE RETAINER LH & RH	2 PC	27.80	
22 REAR BUMPER CLIPS	15 PC	82.50	
23 REAR END PANEL	1 PC	380.20	
24 REAR END PANEL TOP GARNISH	1 PC	66.60	
25 SPARE TYRE PANEL	1 PC	460.80	
26 SPARE TYRE PANEL TOP TRIMBOARD	1 PC	89.20	
27 REAR WINDSCREEN MOULDING (COMPLETE)	1 PC	149.20	
28 REAR FENDER RH	1 PC	1,134.20	
29 REAR FENDER COWLNG RH	1 PC	85.20	
30 REAR FENDER COWLING CLIPS	8 PC	28.00	
31 REAR FENDER AIR VENT RH	1 PC	35.70	
32 REAR FENDER INNER TRIM LH & RH	2 PC	136.60	
33 SPARE TYRE SCREW	1 PC	15.30	
34 REAR CHASSIS RH	1 PC	555.40	
35 REAR EXHAUST PIPE	1 PC	320.40	
36 REAR EXHAUST PIPE MOUNTING	3 PC	46.20	


Ah Lim Motor Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN CHENG KIAT
43 CHUAN GARDEN

SINGAPORE 558560

ATTN:

Your Ref No: SKT3686R
Claim Type: Third Party
Accident Date: 17/10/2021
TP Veh Reg No: YP8371X

Estimate No: MC1902224
Date: 19 Oct 2021
Policy No: MT/00642749/02
Veh Reg No: SKT3686R
Make/Model: HONDA CITY 1.5 SV
CVT

Estimate Repair Cost to Vehicle No :SKT3686R

Description	Quantity	List Price S\$	Amount S\$
		6,837.00	
	Less 20%	1,367.40	5,469.60
Special Nett			
37 REVERSE SENSOR	1 SET	400.00	
38 NUMBER PLATE	1 PC	35.00	
39 INNER SEAL	1 PC	20.00	
40 WINDSCREEN SEALANT	1 PC	40.00	
		495.00	495.00
LABOUR			
41 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
42 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	
43 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	
44 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	120.00	
45 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	280.00	
46 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	
47 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	90.00	
48 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	80.00	
49 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL,SPARE TYRE PANEL,REAR FENDER RH,REAR CHASSIS RH,TAILAMP PANEL LH & RH.TO KNOCK & REPAIR REAR FENDER LH,REAR CHASSIS LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,600.00	
50 TO SPRAY REAR BOOT,REAR BUMPER,END PANEL, SPARE TYRE PANEL,REAR FENDER LH & RH,REAR CHASSIS LH & RH	1 PC	1,400.00	
		3,890.00	3,890.00

Ah Lim  Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN CHENG KIAT
43 CHUAN GARDEN

SINGAPORE 558560

ATTN:

Your Ref No: SKT3686R
Claim Type: Third Party
Accident Date: 17/10/2021
TP Veh Reg No: YP8371X

Estimate No: MC1902224
Date: 19 Oct 2021
Policy No: MT/00642749/02
Veh Reg No: SKT3686R
Make/Model: HONDA CITY 1.5 SV
CVT

Estimate Repair Cost to Vehicle No :SKT3686R


Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 9,854.60
		Add GST @ 7%	689.82
		Total Amount Payable	S\$ 10,544.42

TOTAL: SINGAPORE DOLLAR TEN THOUSAND FIVE HUNDRED FORTY FOUR AND CENTS FORTY TWO ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY


AUTHORISED SIGNATURE

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 975A

Vehicle Details

Vehicle No.: SKT3686R
Vehicle to be Exported: No
Intended Deregistration Date: 19 Oct 2021
Vehicle Make: HONDA
Vehicle Model: CITY 1.5 SV CVT
Primary Colour: Grey
Manufacturing Year: 2015
Engine No.: L15Z12702701
Chassis No.: MRHGM6660GP000041
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$17,647.00
Original Registration Date: 03 Jun 2015
First Registration Date: 03 Jun 2015
Transfer Count: 0
Actual ARF Paid: \$7,647.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 02 Jun 2025
PARF Rebate Amount: \$4,970.00

Intended COE Rebate Details

COE Expiry Date: 02 Jun 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$66,590.00
COE Rebate Amount: \$24,113.00
Total Rebate Amount: \$29,083.00

The information contained herein is correct as at 19 Oct 2021

OK