



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI21010715/Rtf3n2 Date: 18/02/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJM 9769U	Veh. Inspected	FBE 9684S
Policy No.		Coverage (\$)	0.00
Claim No.	C10012019 /JM	Excess (\$)	0.00
Assign From	CHRISTINA	Assign Date	19/10/2021
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA RXZ	c.c	133
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	PMY5PV100A0033902	Colour	MULTI
Odometer	71844 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	80/90-18	FKR	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	90/90-18	FKR	4 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/10/2021	Inspection Date	20/10/2021
Survey held at	22 WOODLANDS LINK #04-30		
Repairer	KAKA MOTO WERKZ		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	