



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21010724/Kuf3e2	
			Date: 17/12/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 812T	Veh. Inspected	SJL 6593J	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/10/21/2029	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	19/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	RN61083829	Colour	METALLIC GREY	
Odometer	180670 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50Z R17	FALKEN	7 mm	
L/H Front Tyre	215/50Z R17	FALKEN	7 mm	
R/H Rear Tyre	215/50Z R17	FALKEN	7 mm	
L/H Rear Tyre	215/50Z R17	FALKEN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/10/2021	Inspection Date	20/10/2021	
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	