

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21010732/T1ty3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 08/11/2021 SINGAPORE 068811 ATTN: ANG YVONNE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHA 4100T** SMN 3804A Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M03K4S Excess (\$) 0.00 ANG YVONNE **Assign Date** 19/10/2021 Assign From **Vehicle Particulars & Condition** 2. TOYOTA PRIUS CVT c.c 1497 Make & Model HIDDEN 2015 Engine No. Year of Reg. JTDKD3B3101570203 SILVER Chassis No. Colour 155427 KM Odometer Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/55 R15 TOURADOR 6 mm 195/55 R15 **TOURADOR** L/H Front Tyre 6 mm 195/55 R15 **TOURADOR** R/H Rear Tyre 6 mm **TOURADOR** L/H Rear Tyre 195/55 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. 5. **General Information** 15/10/2021 20/10/2021 (03:49 PM) **Accident Date** Inspect Date / Time 23 KAKI BUKIT AVE 4 LEVEL 4 SINGAPORE 415933 Survey held at Repairer TEAM MOTION PTE LTD 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

Report Ref No. CS3/ASM21010732/T1ty3e2

Estimate Days of Repair

Inspected By

5b.

MOHAMAD TAUFIKH
M.MATAI. AMSAE-A

Automotive Assessor

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

6 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.