



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21010746/Uuf3e2	
			Date: 15/12/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 4579K	Veh. Inspected	JTP 4796
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/10/21/2025	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	19/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA WAVE	c.c	109
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	PMKJA2650KB413013	Colour	BLACK / YELLOW
	Odometer	24281 KM	Steering	AFFECTED
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	70/90-17	MICHELIN	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	80/90-17	MICHELIN	6 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/10/2021	Inspection Date	20/10/2021
	Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	