



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNA 6767K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RH REAR FENDER	TO REPAIR SEE LABOUR	1,500.50	-
1	RH REAR DOOR	BUCKLED	1,176.20	966.00
1	RH REAR DOOR WINDOW REGULATOR	DAMAGED	648.20	421.70
1	RH REAR DOOR WEATHERSTRIP	TORN	152.10	152.10
1	RH FRONT DOOR	TORN	1,224.20	985.00
1	RH FRONT DOOR WINDOW REGULATOR	DAMAGED	672.40	441.70
1	RH FRONT DOOR WEATHERSTRIP	DEFORMED	158.90	158.90
1	RH FRONT FENDER	BUCKLED	696.50	498.80
1	RH FRONT FENDER INNER SHIELD	DEFORMED	237.80	121.00
1	RH ROCKER PANEL	TO REPAIR SEE LABOUR	588.50	-
1	RH FRONT SHOCK ABSORBER	NOT NECESSARY	547.60	-
1	RH FRONT LOWER ARM	NOT NECESSARY	372.50	-
1	RH FRONT WHEEL BEARING WITH HUB	DAMAGED	394.10	205.00
1	WHEEL HUB CAP	CRACKED	262.20	150.00
	LESS 20% DISCOUNT		-	-820.04
			8,631.70	3,280.16
<u>LABOUR</u>				
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS. INCLUSIVE OF THE REPAIR OF RH REAR FENDER AND RH ROCKER PANEL.		1,440.00	1,000.00
	TO DISMANTLE AND REINSTALL BOTH DOORS COMPONENT.		240.00	120.00
	TO CHECK WIRING AND REWIRE.		60.00	50.00
	TO APPLY ANTI-RUST.		100.00	60.00
	TO PUTTY AND SPRAY-PAINT ON AFFECTED AREAS.		1,300.00	1,200.00
			3,140.00	2,430.00
GRAND TOTAL			11,771.70	5,710.16



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,550.00
---	--	--	-----------------

Report Ref No. CS3/ASM21008601/T1qy3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.