



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2200345

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 17/01/2022
Reference CC4/GRB21010759/Ugs3q2
Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. FBP 8806G
Insured Veh. SLP 6970J
Claim No. MFL2021D0004555
Policy No. D21MFL0000447
Accident Date 15/10/2021
Inspection Date 20/10/2021

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Merimen Fee	11.00
Subtotal	361.00
GST (7%)	25.27
Grand Total	386.27

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM