



ESTIMATE TO REPAIR

VEHICLE NO. : SKS 4185 T
 MAKE : AUDI
 MODEL : A3 SEDAN 1.4 TFSI AMBIENTE MY 15
 YEAR : 2014
 CHASSIS NO : WAUZZZ8V6F1075190

SURVEYOR NAME :
DATE OF SURVEY :
TIME OF SURVEY :

DATE : 19-Oct-21
 DATE OF ACCIDENT : 5-Oct-21
 THIRD PARTY REF : SMP 4076 S / AIG

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	front bumper				\$1,514.50
1 pc	front bumper retainer				\$27.00
1 pc	front bumper reinforcement				\$522.65
1 pc	front bumper fog lamp cover				\$79.55
1 pc	front bumper spray nozzle cover				\$41.10
1 pc	o/s headlamp				\$1,559.85
1 pc	head light bulb				\$500.45
1 pc	o/s headlamp spray nozzle				\$158.65
1 pc	o/s front fender				\$632.75
					\$5,036.50
	less 10%				\$503.65
					\$4,532.85
	To putty and spray paint.				\$600.00
	To check front wiring & focus headlights.				\$30.00
	Labour charges.				\$480.00
TG-ML/-	TOTAL				\$5,642.85