

RE: AUDIT CHECK 2 VEHICLES

Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>

Mon 1/11/2021 5:13 PM

To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>

Hi Denise,

AUDIT CHECK DONE FOR SLM3614Z, FOUND COR RANGE QUOTED TOO HIGH, SHOULD BE 3K -4K, 4 REPAIR DAYS.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Denise Tay (LKKAUTO)

Sent: Monday, 1 November, 2021 4:41 PM

To: Simon Ho (LKKAUTO)

Subject: AUDIT CHECK 2 VEHICLES

Hi Simon,

SMN 3804A - CS3/ASM21010732/T1ty3

SLM 3614Z - CS3/ASM21010776/T1ty3

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)