



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:JANICE			Ref: CC4/ASM21010792/Trs3q2 Date: 15/02/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMN 4661M	Veh. Inspected	FBG 1097D
	Policy No.	GA558679	Coverage (\$)	0.00
	Claim No.	S1M03K7Q	Excess (\$)	0.00
	Assign From		Assign Date	20/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA FZ 16	c.c	153
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	ME121C071C2027269	Colour	RED
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	100/80 R17	MICHELIN	5 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	140/70 R17	MICHELIN	5 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/10/2021	Inspection Date	20/10/2021
	Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	