

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 22-Oct-21 INSURANCE: _____
MODEL: HYUNDAI I40
VEHICLE NO.: SHC 8473 E (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
FRONT BUMPER REINFORCEMENT <i>Deuhl</i>	1	\$ 588.40	\$588.40
ENGINE UNDER COVER <i>hmr</i>	1	\$ 334.60	\$334.60
SUB TOTAL			\$923.00
LESS 20%			\$184.60
DISCOUNTED TOTAL			\$738.40
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance			

Ryan

LKK Ltd

[Signature]