LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Adeline Chng Pei Wen Date: 25 Oct 2021 Attn:

Preliminary Advice

Insured Vehicle No : SMT3341L

TP Vehicle No : SMF3138G Accident Date : 14/10/2021 : MITSUBISHI ATTRAGE : 21/10/2021 Make Assignment Date

Est. Duration of Repair Date of Inspection : 25/10/21 : 3

Inspection At : ACCORD AUTO SERVICES PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,874.06
Revised Amount	:S\$	2,040.42
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,040.42

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
		let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: The above survey was conducted on a 'Without Prejudice' basis. (X)

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost