

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Not Authorized
dhu
26/10/21
2/s # 24,000
5 days.

VEHICLE No: XE 6868M

1PC	FRONT BUMPER	DIS	2200.83	\$2,886.01	/
1PC	FRONT BUMPER TOP SIDE PROTECTOR N/S	waped	457.20	\$485.21	/
1PC	FRONT BUMPER SIDE BLACK GARNISH N/S	DIS	140.29	\$198.00	/
1PC	FRONT BUMPER HEADLAMP GARNISH N/S	one		\$250.00	/
1PC	FRONT BUMPER FOG LAMP GARNISH N/S	one	153.63	\$220.00	/
1PC	HEADLAMP N/S	17	148.21	\$1,272.03	X
1PC	FRONT FOG LAMP N/S	17		\$361.67	X
1PC	FRONT STEP PANEL LOWER N/S	one	594.41	\$750.00	/
1PC	FRONT STEP PANEL REFLECTOR N/S	17		\$60.00	X
1PC	FRONT STEP LOWER GARNISH N/S	one	953.10	\$988.10	/
1PC	FRONT STEP CENTER PANEL N/S	17		\$1,280.10	X
1PC	FRONT STEP PANEL CENTRE GARNISH N/S	one	1145.21	\$1,256.80	/
1PC	FRONT DOOR N/S	R		\$5,542.31	X
1PC	FRONT WHEEL ARCH GARNISH N/S	waped / torn	1045.35	\$1,160.26	/
1PC	FRONT WHEEL ARCH PROTECTOR N/S	groat	645.21	\$845.21	/
1PC	FRONT WHEEL MUDFLAP N/S	torn	305	\$350.00	/
1PC	FRONT DOOR MIRROR BLACK BRACKET N/S	R		\$675.10	X
1PC	FRONT DOOR PILLAR N/S	R		\$1,160.10	X
				\$19,740.90	
	S.NETT				
1SET	REAR WIRELESS REMOTE CONTROL CANVAS ASSY	waped / torn		\$28,000.00	22,000
1PC	N/S SLIDING RAILING ASSY	R		\$2,500.00	X
	TO CHECK WIRING			\$50.00	20
	TO SPRAY RUST PROOFING			\$80.00	30
	TO DISMANTLE & REPLACED REAR CANVAS ASSY			\$1,200.00	500
	TO RESET & REPROGRAMME SYSTEM			\$200.00	X
	LABOUR FOR PANEL BEATING & REPLACED PARTS			\$1,800.00	800
	TO PUTTY & SPRAY PAINTING			\$1,500.00	850
	TOTAL			\$55,070.90	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1-7790.44
257
9-5842.83
S.N-22,000
1-2220
30042.83
202
24034.