

Estimate

20/10/2021

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Page # :- 1

Veh # :- SMF8845R

Veh Model :- HONDA CIVIC 1.6 VTI CVT

Estimate# :- CK422419

Claim # :-

ACC. Date :- 15/10/21

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR WINDSCREEN GLASS MOULDING <i>na</i>	1 PC	185.20	185.20
2.	REAR FENDER RH <i>blue</i>	1 PC	1,041.10	1,041.10
3.	REAR FENDER COWLING RH <i>? x on</i>	1 PC	63.10	63.10
4.	REAR SPORT RIM RH <i>sa</i>	1 PC	604.00	604.00 <i>300 s/n</i>
5.	REAR WHEEL BEARING RH <i>x on</i>	1 PC	363.30	363.30
6.	REAR BUMPER <i>sa</i>	1 PC	617.00	617.00
7.	REAR BUMPER RETAINER RH <i>? x on</i>	1 PC	21.30	21.30
8.	REAR BUMPER CLIPS <i>na</i>	10 PC	5.50	55.00
9.	REAR SHOCK ABSORBER RH - CHECK <i>x na</i>	1 PC		
10.	TAILLAMP RH - CHECK <i>x na</i>	1 PC		
	LIST TOTAL S\$		1898.30	2,950.00
	20% DISCOUNT S\$			-590.00
			1518.64	2,360.00
SPECIAL NET ITEMS :				
1.	REAR WINDSCREEN GLASS SEALANT <i>na</i>	1 PC	40.00	40.00
	SPECIAL NET TOTAL S\$			40.00
LABOUR :				
	TO CUT/WELD REAR FENDER RH, KNOCK & STRAIGHTEN REAR BODY MEMBER. REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION			
	SPRAY PAINT REAR FENDER RH, REAR END PANEL TAILLAMP PANEL RH, REAR BUMPER ROCKER PANEL RH			
	REMOVE & REPLACE REAR WINDSCREEN GLASS & CHECK WATER LEAKAGE			
	REMOVE & REPLACE REAR SPEAKER BOARD, REAR SEAT ASSY, REAR FLOOR CARPET, UPHOLSTERY			
	REMOVE & REPLACE REAR UNDER CARRIAGE SUSPENSION RH			
	LABOUR TOTAL S\$			
			1518.64	
			340.00	
			1180.00	
			3038.64	
			20%	
			2430.91	
			48 - \$2,400	
				600 800.00
				400 700.00
				120.00
				60 150.00
				M X 150.00
				1,930.00