



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD
#02-01 UOI BUILDINGSINGAPORE 068909

Ref: CS/UOI21010895/Uuf3e2

Date: 09/11/2021

Code: UOI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 5644D	Veh. Inspected	FBN 3461K
Policy No.		Coverage (\$)	0.00
Claim No.	M12D16872111	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	25/10/2021

2. Vehicle Particulars & Condition

Make & Model	YAMAHA YBR 125	c.c	124
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	LBPRES101000059580	Colour	BLACK
Odometer	88682 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	2.75-18	TIMSUN	7 mm
L/H Front Tyre			mm
R/H Rear Tyre	3.00-18	TIMSUN	7 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION AND N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/10/2021	Inspection Date	25/10/2021
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**