

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 25.10.21

INSURANCE: AIG ASIA

MODEL: Hyundai Ioniq

MVA: LIM T S

VEHICLE NO.: SHA1145J

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper <i>de ✓</i>	1		\$459.40
	Rear Bumper Reflector RH <i>? X m</i>	1		\$41.45
	Rear Bumper Centre Moulding-Black <i>sc ✓</i>	1		\$451.25
	Rear Bumper Side Bracket RH <i>? X m</i>	1		\$138.10
	Rear Bumper Clips <i>sc ✓</i>	10	\$2.20	\$22.00
	SUB TOTAL			\$1,112.20
	LESS 20% DISCOUNTED TOTAL			\$222.44
				\$889.76
	S/NETT TOTAL			\$-
	SPARE PARTS TOTAL			\$889.76
	Labour Charge			
	Panel Beating			\$400.00
	Spray Painting Charge-Rear Fender RH			\$600.00
	Remove/Refix Reverse Sensor			\$120.00
	TOTAL LABOUR			\$1,120.00
	ESTIMATE TOTAL			\$2,009.76

932.65
20%
746.12

350 }
500 } 890
40 }

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
3 days
P/P
25/10/21 @ 1630
Resurvey before paint

746.12
890.00
1636.12