

Soon Seng Company (SG) Pte Ltd

160 Sin Ming Drive
#04-05
Sin Ming Autocity
S575722

Our client SJS4346H
TP claim against INDIA Insurance (Your insured: SLV6958P)

Not Notched
L1 Ry @ 2450k 2400.00
Resurvey After Paint
4 days

Hennerh
96910663

Repairer's estimate

Parts

1	Rear taillight LH	345	My 2M	1	650	650	X
2	Rear taillight RH	345	7	1	650	650	X
3	Rear tail light bracket			2	180	360	X
4	Rear bumper reflector			2	85	170	X
5	Rear bumper	477		1	760	760	X
6	Bumper clips			10	3	30	X
7	Rear bumper retainer			2	64	128	X
8	Rear reinforcement bar			1	635	635	X
9	Rear End Panel	366.10		1	722	722	X
10	Reverse sensors	sn	Shog A	1	100	400	X
11	Rear Boot Lid			1	955	955	X
12	Boot lid garnish			1	264	264	X
13	Rear emblems			3	60	180	X
14	Rear boot MID TRIM			1	150	150	X
15	Rear boot lock	189.90		1	220	220	X
16	Rear boot cabin middle garnish			1	163	163	X
17	Rear boot cabin inner left side garnish			1	328	328	X
18	Rear boot cabin inner board and foam			1	295	295	X
19	Rear exhaust muffler			1	1250	1,250	X
20	Bootlid weatherstrip			1	232	232	X
21	Rear reinforcement support brace			2	135	270	X
22	LH Taillight panel			1	280	280	X
23	Windscreen gum	sn		2	80	160	X
24	Silicone waterproofing gum	sn		2	80	160	X
Parts Total:					\$ 9,412.00		

258

Labor

1	Check wiring and system function			1	200	200	15h
2	Rust proofing on affected areas			1	400	400	30l
3	Labor to remove and refit reinforcement bar, rear boot, rear bumper, tail lights			1	1000	1,000	1600l
4	To cut and weld rear end panel			1	700	700	X
5	Wheel alignment			1	150	150	X
6	To respray damaged and refitted parts (inner end panel respray, rear bumper, rear boot)			1	900	900	600l
Labor Total:					\$ 3,350.00		

TOTAL: \$12,762.00

*Supplementary items would be included if noticed during the course of repair

Contact:
James - 92960289
Mr Chai - 96250518

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: