

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Ms.
PADMINI
D/O KUNCHI KANAN
BLK 107 BUKIT BATOK WEST AVE 6
#09-112
SINGAPORE 650107

Document no.
Document date 25-10-2021
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2021040420/ 1
Job order date 25-10-2021
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SLP7493M	5G13HZ	16-06-2017	WWWZZZAUZHW119666	Golf 1.4 CLBM 92 TSI D7F	56,680

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
9801B003	B&P WHEEL ALIGNMENT				#1	360.00	385.20
9801B001	R&R RIM & BALANCE				#1	50.00	53.50
5G0807217BNGRU	Cover For Bumper Primed	1	pcs.	1,317.70	#1	1,317.70	1,409.94
5G0807724D	Support Part	1	pcs.	59.30	#1	59.30	63.45
5G0807050A	RHS BUMPER INNER BRACKET	1	pcs.	22.85	#1	22.85	24.45
	Guide Piece	1	pcs.	22.85	#1	22.85	24.45
5G0919493	Sensor Bracket	1	pcs.	15.02	#1	15.02	16.07
5G0919494	Sensor Bracket	1	pcs.	15.02	#1	15.02	16.07
5G0919493A	Sensor Bracket	2	pcs.	15.02	#1	30.04	32.14
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	81.39	#1	81.39	87.09
D 822150A1	Bonding Agent For Plastic	1	pcs.	65.42	#1	65.42	70.00
5G2941006E	Twin Halogen Headlamps	1	pcs.	766.75	#1	766.75	820.42
6R0973735	RHS H/LAMP	1	pcs.	21.17	#1	21.17	22.65
5G0821106A	Flat Contact Housing	1	pcs.	631.36	#1	631.36	675.56
5G0821136B	H/LAMP WIRE HOUSING	1	pcs.	34.34	#1	34.34	36.74
N 90817302	Fender	1	pcs.	2.50	#1	10.00	10.70
5G0805970N	Cross Support	1	pcs.	188.98	#1	188.98	202.21
5G2857508BG9B9	RHS FENDER BRACKET	4	pcs.	597.87	#1	597.87	639.72
5G0857538E GRU	Riveted Cap Nut	1	pcs.	180.60	#1	180.60	193.24
5G0857522A	Wheelhouse Liner	1	pcs.	197.66	#1	197.66	211.50
5G0845412E NVB	RHS FENDER LINER (UPPER)	1	pcs.	131.89	#1	131.89	141.12
D 169300M2	Rear View Mirror Housing	1	pcs.	51.30	#1	51.30	54.89
D 002000A2	RHS MIRROR HOUSING	1	pcs.	119.97	#1	119.97	128.37
D 00920002	Mirror Cap Primed	1	pcs.	28.52	#1	28.52	30.52
D 181802M1	RHS MIRROR COVER	1	pcs.	26.23	#1	26.23	28.07
D 00950025	Mirror Glass	2	pcs.	10.47	#1	20.94	22.41
5G4837432K 5AP	MIRROR GLASS	1	pcs.	250.25	#1	250.25	267.77
5G6839902B 041	Side Window	1	pcs.	97.89	#1	97.89	104.74
5G0601025BTFZZ	RHS A-PILLAR GLASS	1	pcs.	1,461.36	#1	1,461.36	1,563.66
311601361	1k Window Adhesive	1	pcs.	3.61	#1	3.61	3.86
	Adhesive Remover	1	pcs.	840.00	#1	840.00	891.60
	Primer	1	pcs.				
	Activator For Precoated W	1	pcs.				
	Applicator	2	pcs.				
	Glass Channel Black	1	pcs.				
	RHS FRT DOOR CHANNEL SEAL	1	pcs.				
	Trim For Door Window Fram	1	pcs.				
	RHS REAR DOOR SIDE TRIM (BLACK)	1	pcs.				
	Alloy Wheel Aluminium Shi	1	pcs.				
	Rubber Valve	1	pcs.				
	LABOUR	4	pcs.				

VOLKSWAGEN CENTRE SINGAPORE

47 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Ms.
PADMINI
D/O KUNCHI KANAN
BLK 107 BUKIT BATOK WEST AVE 6
#09-112
SINGAPORE 650107

Document no.
Document date 25-10-2021
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2021040420/ 1
Job order date 25-10-2021
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SLP7493M	5G13HZ	16-06-2017	WVWZZZAUZH119666	Golf 1.4 CLBM 92 TSI D7F	56,680

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Spray Painting	5	pcs.	800.00	#1	4,000.00	4,280.00
	R&R RHS MIRROR HOUSING	1	pcs.	840.00	#1	840.00	898.80
	R&R RHS A-PILLAR GLASS	1	pcs.	840.00	#1	840.00	898.80
	CHINA TAIPING DIRECT SETTLEMENT						
	DOA: 22/10/2021						
	TP VEH: GBF4779E						
	SURVEY BY:						

Quotation valid till 01-11-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	1,170.00	15,467.43	7%	1,164.62	16,637.43	17,802.05
Total	1,170.00	15,467.43		1,164.62	16,637.43	17,802.05

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: