

Hui Zhen (LKK Auto)

From: Hui Zhen (LKK Auto)
Sent: Thursday, 2 December 2021 10:45 AM
To: EUROSUCCESS0202@GMAIL.COM; SUR
Subject: OD/ SMW 551B / DOA: 9/1/2021

Dear Sir/Mdm,

As instructed by our client , please proceed to repair the **insured vehicle SMW 551B at repair cost not more than \$50,000 on Lump sum basis, (Excess \$1000).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Hui Zhen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: huizhen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)