



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS21010929/Uqf3e2	
			Date: 07/01/2022	
			Code: AIS	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SMW 551B
	Policy No.	SP2000135171-01	Coverage (\$)	0.00
	Claim No.	2021 20002322	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	26/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 535i A (A)	c.c	2979
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	WBAFR72030C580653	Colour	BROWN
	Odometer	-	Steering	AFFECTED
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/35Z R20	PIRELLI	9 mm
	L/H Front Tyre	MISSING		mm
	R/H Rear Tyre	275/30Z R20	PIRELLI	9 mm
	L/H Rear Tyre	275/30Z R20	PIRELLI	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY, N/S FRONT, FRONT, REAR, O/S REAR PORTION AND ROOFTOP. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/01/2021	Inspection Date	26/10/2021
	Survey held at	EURO SUCCESS SERVICES PTE LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A) THE MARKET VALUE IS S\$95,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		35 Working Days	