

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	STRIDES AUTOMOTIVE SERVICES PTE LTD		Ref:	CS/SMR21010934/Buf3e2		
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 7705	Date:	09/11/2021		
			Code:	SMR		
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SG 5159G	Veh. Inspected	SMX 3681J		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	BUS/10/21/5035	Excess (\$)	0.00		
	Assign From	HUA YEN	Assign Date	26/10/2021		
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL 1.5X	c.c	1496		
	Engine No.	HIDDEN	Year of Reg.	2021		
	Chassis No.	RU11331274	Colour	GREEN		
	Odometer	15955 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	FAIR				
3. Conditions of Tyres						
		Size	Make	Balance		
	R/H Front Tyre	215/60 R16	DUNLOP	6 mm		
	L/H Front Tyre	215/60 R16	DUNLOP	6 mm		
	R/H Rear Tyre	215/60 R16	DUNLOP	6 mm		
	L/H Rear Tyre	215/60 R16	DUNLOP	6 mm		
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	24/10/2021	Inspection Date	26/10/2021		
	Survey held at	TEAM AUTOPRO PTE LTD				
		160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722				
5a.	. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
	B)III / IOOO I IB/ II IO		Estimate Days of Repair			
	2/11/1000112/1110	Estimate	Days of Repair			