ASS. REC. BY: Tautin REF: C3/ASM21010956/71+43 2022 NOV ASSIGNMENT SG 7 9114B. Yr Regn: 2007, NOV Date: Veh No: Estimated Cost: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / OD TO INSITE RESIDE RESIEVA INVINV Truck / Trailer or To Inspect Vehicle No: Mákė: at Workshop m/s White A/C: Insured / Std / NI / NA Colour T/Radio: Insured / Std / NI / NA Sp.Reading Insured: Eng/No: JM6BR1062805775 Policy No. Gen. Cond: God / Fair / Poor / Burnt Claims No. Steering: Inorder / Jammed / Leaked / Burnt or Sum Insured: Excess: Brake: Inorder / Jammed / Leaked / Burnt or (Client's Record) Modi: NII / SEPT / STD A/Rim or Make of Veh; Tyre Size: (Policy Condition) Remark: The veh had commenced its OIS BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / Continental repair at the time of inspection. TOYO / YOKO or 49K Bal. or Market Value: Front Consistent? : Yes or No R/Bal. IDAC Accident Roort: Consistent?: Yes or No L/Bal. UBal. GIA / PR Seen: D.O.A. Est. Repairs: days Res.: Yes or No 3 Val.: Yes or No Lum Sum: Survey held at w/ ··· Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT Person Contacted: Dale: The U/C / Chassis frame / Body Structure affected due to collision. Action / Instruction Date / Time Lump sum \$4000, 6days red: 10,507.2;72% Date/Time, File Pass to? : Prell. Report 6 Days Of Repair: : Final Report Resurvey No. of Trip: Date/Time, File Return to? Survey Fee: Transportation:

Add Fee:

Representation

Lump Sum / LE A: (7)

: Site insp (\$

: Interview (\$

Tech. Invs (\$

Wedlend (\$

_S+RS__ SI

Pholos

Othera

TOTAL

TSL Auto Garage Blk 4 Joo Chiat Complex #12-1171 Joo Chiat Road Singapore 420004

3GL	SGZ9114B Mazda 3 Estimated			stimated
NT-	04	Parts Description	Pa	rts Price
No 1	Qty 1	Parts Description Front bumper assy	\$	1,250.0010 4× 166.00km de 4× 166.00 RHW
2	2	Front bumper retainer	\$ P.	4× 166.00 KH de
3	2	Front bumper bracket	SRI	1 × 166.00 RHM
4	1	Front bumper lower grille	\$	291.00 ×
5	1	Front bumper reinforcement	\$	378.00 ht
6	1	Front bumper tow cover	\$	88.00 ×
7	1	Front left fog lamp	\$	240.00×
8	1	Front left fog lamp garnish	\$	68.00 ×
9	1	Front grille assy	\$	382.00 ⊀
10	1	Front grille emblem	\$	106.00 ≺
11	1	Front bonnet assy	\$	1,431.00 67
12	1	Front bonnet lock	\$	179.00⊀
13	1	Front bonnet lock catch	\$	36.00×
14	1	Front lock brace panel	\$	123.00⊁
15	1	Front left headlamp	\$	1,498.00 Cm
16	1	Front left headlamp inner bracket	\$	1,498.00cm 95.00 de 1,195.00 zug
17	1	Front support panel assy	\$	1,195.00 Zuq/
18	1	Front left suspension assy	\$	832.00×
19	1	Front left lower arm	\$	420.00 X
20	1	Front left knuckle arm	\$	425.00
21	1	Front left wheel hub with bearing	\$	250.00♀
22	1	Front left fender lamp	\$	68.00×
23	1	Front left fender	\$	897.00h7
		,	\$	10,584.00
		less 20%	\$	2,116.80
			\$	8,467.20
		Special Nett Items		
1	12	Front bumper clips	\$	60.00 %
2	6	Front bumper lower grille clips	\$	40.00 ×
3	6	Front grille clips	\$	40.00 X
4	1	Front no plate	\$	100.00 ⊀
5	1	Front left wheel rim	\$	680.00 ×
6	1	Front left tyre	\$	300.00⊀
7	1	Front no plate with garnish	\$	100.00 ×
8	1	Front bumper lower spoiler	\$	000.00 %
9	1	Front bumper lower spoiler sealant		100.00 40.04
0	10	Front bumper lower spoiler clips	\$	880.00 de / 40 100.00 Ho 4 50.00 20m
. T	10	- 10 m ounipor tower sporter clips	\$	
			_2	2,350.00
		Total parts	\$	10,817.20

TSL Auto Garage Blk 4 Joo Chiat Complex #12-1171 Joo Chiat Road Singapore 420004

SGZ9114B Mazda 3

	A STATE OF THE PERSON OF THE P		Labour
No	Description	ingio anesa	Charges
1	Labour for panel beating, cut, weld, straighten front affected area	\$	1,400.00
	and replace front damaged parts.		
2	To putty and spray painting front portion.	\$	_{1,400.00} 80ට
3	To check wiring and focus front headlamp.	\$	50.00 30
4	To remove and install front bonnet lock mechanism.	\$	80.00
5	To apply anti rust proofing to front affected area.	\$	140.00 30°
6	To remove and install front left undercarriage parts.	\$	350.00×
7	To balance front left wheel.	\$	50.00⊀
8	To conduct wheel alignment.	\$	120.00〆
9	Towing service.	\$	100.00 🔨
	Total labour :	\$	3,690.00

Taufth 97495749

Who Penny you repair
tempth althantourn
obdays

Repair Vinit 94000

MV 9K
Nebale 4478

Total parts: \$ 10,817.20

Total labour: \$ 3,690.00

Total repair cost: \$ 14,507.20

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed ? is subject to final approval from Insurance

Acknowledged by Repairer

Signature:

Date:

I Vehicle Owner Particulars Owner ID Type: Singapore NRIC 567D Owner ID: | Vehicle Details Vehicle No.: SGZ9114B Vehicle to be Exported: No Intended Deregistration 28 Oct 2021 Date: Vehicle Make: MAZDA Vehicle Model: MAZDA3 SP Primary Colour: White Manufacturing Year: 2007 Engine No.: Z6614119 Chassis No.: JM6BK106280377554 Maximum Power Output: 79.0 kW (105 bhp) Open Market Value: \$14,391.00 22 Nov 2007 Date: First Registration Date: 22 Nov 2007 Transfer Count: 1 Actual ARF Paid: \$15,831.00 Ilinterided PARF Rebate Details PARF Eligibility: Forfeited PARF Eligibility Expiry Date: PARF Rebate Amount: \$0.00 Illintended COE Rebate Details® COE Expiry Date: 21 Nov 2022 COE Category: A - Car (1600cc & below) COE Period(Years): PQP Paid: \$20,997.00 COE Rebate Amount: \$4,478.00 **Total Rebate Amount:** \$4,478.00

IMessage[®]

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 28 Oct 2021

Original Registration

Mazda 3 1.6A SP (COE till 10/2022)

Overview

Financial

Accessories

es Similar

Research

Photos

os Map



STARISE AUTOMOBILE

William Co.

Accredited by

Price	\$8,800		
Depreciation	\$8,780 /yr:	Reg Date	30-Oct-2007 (1yr1day COE left)
Mileage	N.A.	Manufactured 5	2007
Road Tax	\$1,039 /yr	Transmission	Auto
Dereg Value	\$4,268 as of today (change)	OMV @	\$14,482
COE	\$21,282	ARE :	\$15,931
Engine Cap	1,598 cc	Power	79.0 kW (105 bhp)

No. of Owners

Features

Curb Weight

Type of Vehicle

1,235 kg

MId-Sized Sedan

Powerful And Responsive 1.6L DOHC 16V VVT Engine, 4 Speed Automatic Steptronic Transmission, 2 x SRS Airbags And ABS. View specs of the Mazda 3 Sedan (2604-2609).

Accessories

Factory Fitted Audio With Multi-Function Control Steering. Premium Black Leather Upholstery, Parking Sensors And Solar Film.

Description

Smooth Engine, Good For Short Term Drive, Cheaper Than Renting A Car, Very Well Taken Care Of And Beautifully Maintained By Previous Owner, Flexible Loan Available, Trade in Welcome, Door Step Viewing Can Be Arrange, Call For Viewing Before It is Sold.

Category

COE Car

Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes:

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally, Find out more

Posted on 12-Oct-2021 | Last Undated on 10-Oct-2921

Upfront Payment (7	— ———————————————————————————————————	➤ nxxe Financial info
Downpayment	Based on 30% downpayment, 70% Loan (Change).	\$2,640
1st Instalment	Based on 3.25% interest rate	
● OCBC Bank	Get an instant car loan at 1.88% p.a. T&Cs apply.	\$530
Total Upfront Payment	Excludes insurance Check with seller for exact figure	\$3,170







Shortlist

(1) Compare

(1) Report Error

(··) More



Starise Automobile

24 valuates for asia 38 sold in past 3 mths

210 Turf Club Road Lot 847/851 Car Mall @ The Grandstand Tel 64697277 Search cars nearby

Louis
Aaron Tan
Kit

98163963 **3** 98797788 **3** 88777822 **3**

