



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21010991/R1uf3n2	
			Date: 02/12/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 1128D	Veh. Inspected	YQ 4370U	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/10/21/2033	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	27/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER FEB21ER	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	FEB21EA35573	Colour	WHITE	
Odometer	2511 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/85 R15	YOKOHAMA	7 mm	
L/H Front Tyre	195/85 R15	YOKOHAMA	7 mm	
R/H Rear Tyre	195/85 R15 (D)	YOKOHAMA	7/7 mm	
L/H Rear Tyre	195/85 R15 (D)	YOKOHAMA	7/7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/10/2021	Inspection Date	01/11/2021	
Survey held at	GOLDBELL ENGINEERING PTE LTD 10 TUAS AVE 18 SINGAPORE 638894			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	