

GBE 9874K

PARTS				S/N		LABOUR	SUPP (PARTS)	
	\$656.20	\$0.00	\$0.00		\$30.00	\$700.00		\$0.00
	\$182.70	\$0.00	\$0.00		\$15.00	\$600.00		\$0.00
	\$80.00	\$0.00	\$0.00		\$120.00	\$120.00		\$0.00
	\$1,755.00	\$0.00	\$0.00		\$60.00	\$50.00		\$0.00
	\$320.00	\$0.00	\$0.00		\$200.00	\$60.00		\$0.00
	\$82.00	\$0.00	\$0.00		\$300.00	\$40.00		\$0.00
	\$60.00	\$0.00	\$0.00		\$0.00	\$30.00		\$0.00
	\$172.00	\$0.00	\$0.00		\$0.00	\$50.00		\$0.00
	\$365.60	\$0.00	\$0.00		\$0.00	\$0.00		\$0.00
	\$385.00	\$0.00	\$0.00		\$0.00	\$0.00		0%
	\$596.00	\$0.00	\$0.00		\$0.00	\$0.00		\$0.00
	\$310.20	\$0.00	\$0.00		\$0.00	\$0.00	SUPP (SN)	
	\$0.00	\$0.00	\$0.00		\$0.00	\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00	\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00	\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00	\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$725.00	\$1,650.00		\$0.00
	\$0.00	\$0.00	\$0.00					
	\$0.00	\$0.00	\$0.00				SUPP(LABOUR)	
	\$0.00	\$0.00	\$0.00				TOTAL	\$0.00
	\$0.00	\$0.00	\$0.00				\$3,723.53	\$0.00
	\$0.00	\$0.00	\$0.00				\$725.00	\$0.00
	\$0.00	\$0.00	\$0.00				\$1,650.00	\$0.00
	\$0.00	\$0.00	\$0.00				SUPP	\$0.00
	\$0.00	\$0.00	\$0.00				TOTAL SUPP	\$0.00
	\$0.00	\$0.00	\$0.00				P/P	\$6,098.53
	\$0.00	\$0.00	\$0.00				MAKE / MODEL	T.HIACE - 2982cc
	\$0.00	\$0.00	\$0.00				MARKET VALUE	\$0.00
	\$0.00	\$0.00	\$0.00				80% LTA REBATE	\$0.00
	\$0.00	\$0.00	\$4,964.70				\$4,878.82 NETT VALUE	\$0.00
	\$0.00	\$0.00					L/S	\$4,900.00
	\$0.00	\$0.00	\$4,964.70				RED	\$3,689.65
	\$0.00	\$0.00	75%				43%	
	\$0.00	\$0.00	\$3,723.53				TOTAL TP EST	\$8,589.65
							REPAIR DAYS	6
							REMARKS	