



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM21011012/Ups3q2 Date: 16/03/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHA 7500C	Veh. Inspected	FBK 8076Y
	Policy No.	P2419138	Coverage (\$)	0.00
	Claim No.	S1M03KQN	Excess (\$)	0.00
	Assign From		Assign Date	27/10/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	YAMAHA FZN150	c.c	149
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	ME1RG1614F2001742	Colour	GREY
	Odometer	93395 KM	Steering	AFFECTED
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	110-70-17	MAXXIS	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	140-70-17	MAXXIS	6 mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	23/10/2021	Inspection Date	27/10/2021
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	