

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

EQ Insurance Co. Ltd
 22 Gemmill Lane
 Singapore 069257
 Tel : 6223 - 9433
 Fax : 6224 - 3903

Hui Zhen

Quotation
 DATE : 01.11.2021
 VEH NO : GBD9141Y
 MODEL : Toyota Hiace
 D O A : 26.10.2021
 YR REF : GBE3258D

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR GBD9141Y (TOYOTA HIACE)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Sliding Door - LH <i>Dented</i>	1	1,455.60 ✓
2	Sliding Door Centre Roller - LH <i>fix new</i>	1	213.40 x
3	Sliding Door Lower Roller - LH	1	278.20 x
4	Sliding Door Lock - LH <i>Damaged</i>	1	289.10 ✓
5	Sill Panel - LH <i>Repair</i>	1	879.80 x
			\$ 3,116.10
Less 25%			(779.03)
			\$ 2,337.08
<u>S/NET ITEMS</u>			
1	Sliding Door Decorative Stickers - LH <i>Net</i>	1 set	350.00 <i>200</i>
			\$ 350.00
Total Parts			
			\$ 2,687.08
<u>LABOUR CHARGE</u>			
1	To knocking & pull out LH side portion & renew above parts		\$ 600.00 <i>300</i>
2	To putty & spray up paint works		\$ 600.00 <i>350</i>
3	To check wiring		\$ 50.00 <i>30</i>
4	To spray tuff coat		\$ 100.00 <i>30</i>
5	To transfer sliding door hitting		<i>150</i> <i>80</i>

RE : ESTIMATE FOR ACCIDENT REPAIR GBD9141Y (TOYOTA HIACE)

Total Labour	\$	1,350.00
Grand Total	<u>\$</u>	<u>4,037.08</u>

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 2318.52
L/S: 1850.
03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: