

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0439/2021/ZK
DATE : 22-May-21
WIP : 28845

\$6613.50

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 29/10/2021
YOUR INSURED VEH NO : SLV 6530 P

MSIG INSURANCE (SINGAPORE) PTE LTD

NO 4 SHENTON WAY

#23-01 SGX CENTRE 2

SINGAPORE 068896

Attn: Motor Claims Dept

Tel: 6827 27692 - Fax: 6225 7402

Hui Zhen.

OWNER'S NAME : MR LIM BOON KENG
ADDRESS : 139 SERANGOON AVE 3
#16-02
SINGAPORE 556119
TELEPHONE : HP +65 9750 9390
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5109016743-02
VEHICLE NO : SDK 8811 T
MODEL CODE : AUDI Q3 1.4 TFSI S
MODEL YEAR : 26/1/2016
ENGINE NO : CZD221231
CHASSIS NO : WAUZZZ8U4GR053215
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Oct-21
PLACE OF ACCIDENT : THOMSON GREEN
TRAFFIC JUNCTION TURNING RIGHT INTO HOUGANG STREET 21



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDK 8811 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION	S/N \$ 280.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	800 ✓
3	TO RESPRAY REAR UPPER BUMPER, REAR LOWER SPOILER AND BOTH REAR WHEEL ARCH TRIMS.	\$ 3,000.00	2200 ✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,672.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDK 8811 T

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Repair</i>	1	\$ 1,580.00	X	
2	REAR BUMPER FIXING SET <i>new</i>	1	\$ 124.00	X	
3	REAR BUMPER SPOILER <i>Del'd</i>	1	\$ 880.00	✓	880
4	REAR BUMPER DIFFUSER - LH <i>Del'd</i>	1	\$ 706.00	✓	705.50
5	REAR BUMPER TOWING EYE COVER - LH <i>Del'd</i>	1	\$ 43.00	✓	42.60
6	REAR TAIL LIGHT - LH <i>Cracked</i>	1	\$ 457.00	✓	457
7	REAR BUMPER CARRIER <i>new</i>	1	\$ 651.00	+	
8	HEX BOLT <i>new</i>	6	\$ 30.00	X	
9	REAR BUMPER PARKING AID SENSOR <i>new</i>	2	TBC	+	
10	REAR BUMPER PARKING AID SENSOR SEAL <i>new</i>	4	\$ 6.00	+	
11	REAR BUMPER WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$ 1,056.00	✓	1055
12	SUNDRIES <i>new</i>		\$ 250.00	✓	1.40
TOTAL SPARE PARTS		:	\$ 5,783.00		
TOTAL LABOUR CHARGES		:	\$ 4,672.00		
GRAND TOTAL		:	\$ 10,455.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Xing Guoqiang*
 SURVEYED DATE :
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *Not Authorised, 93 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT