



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC21011059/Euf3n2	
			Date: 09/12/2021	
			Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SDD 125E
	Policy No.	Z21VP05029264	Coverage (\$)	0.00
	Claim No.	212121VP05025090	Excess (\$)	1,000.00
	Assign From	GERALD POH	Assign Date	28/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 730LI	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	WBA7E02070G245475	Colour	BLACK
	Odometer	33935 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/50 R18	CONTINENTAL	5 mm
	L/H Front Tyre	245/50 R18	CONTINENTAL	5 mm
	R/H Rear Tyre	245/50 R18	CONTINENTAL	5 mm
	L/H Rear Tyre	245/50 R18	CONTINENTAL	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/10/2021	Inspection Date	08/11/2021
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks				
	A)THE MARKET VALUE IS S\$195,000.00 (EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	