

T K LEE AUTOMOTIVE PTE LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

Submit to insurance.

Take the other report

Not Allowed

29/10/21

1/5 6300

7 days

The Motor Claims Dept.

M/S SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE

#03-03 SINGAPORE LAND TOWER

SINGAPORE 048623

SJU5334A

ESTIMATE

DATE : 29.10.2021

VEHICLE NO : SJM9108C

MAKE/MODEL : CHEVROLET OPTR.

ACC DATE : 27.10.2021

PARTICULAR

QTY	Nett Item	UNIT PRICE	AMOUNT
		S\$	S\$
1	1 REAR BOOT LID <i>do/bent</i>	1,028.00	1,028.00 ✓
2	1 REAR BOOT LOGO <i>nee</i>	68.00	68.00 ✓
3	1 REAR BOOT EMBLEM 'CHEVROLET' <i>nee</i>	58.00	58.00 ✓
4	1 REAR BOOT EMBLEM 'OPTRA' <i>nee</i>	42.00	42.00 ✓
5	1 REAR BOOT EMBLEM 'GIS' <i>nee</i>	35.00	35.00 ✓
6	1 REAR BOOT EMBLEM 'MAGNUM' <i>nee</i>	35.00	35.00 ✓
7	1 REAR BOOT OUTER GARNISH <i>11</i>	162.00	162.00 X
8	1 REAR BOOT INNER LOCK <i>surf</i>	186.00	186.00 ✓
9	1 REAR BOOT INNER TRIM <i>11</i>	289.00	289.00 X
10	10 REAR BOOT INNER TRIM CLIPS <i>11</i>	4.50	45.00 X
11	1 REAR BOOT WITH STRIP weatherstrip <i>twi</i>	136.00	136.00 ✓
12	2 REAR BOOT HINGES RH/LH <i>11</i>	155.00	310.00 ✓
13	2 REAR BOOT STOPPER <i>11</i>	10.50	21.00 ✓
14	1 REAR BOOT LOCK STRIKER <i>11</i>	42.00	42.00 X
15	1 REAR BUMPER ASSY <i>dis</i>	1,202.00	1,202.00 ✓
16	1 REAR END PANEL <i>bed gap</i> <i>545</i>	680.00	680.00 ✓
17	1 REAR END PANEL GARNISH <i>twi</i>	122.00	122.00 ✓
18	1 REAR EXHUAUST SILENCER <i>surf/twi</i>	635.00	635.00 ✓
19	1 REAR EXHUAUST SILENCER GASKET <i>nee</i>	28.00	28.00 ✓
20	2 REAR EXHUAUST MOUNTINGS <i>11</i>	28.00	56.00 X
21	1 REAR EXHUAUST INSULATOR <i>11</i>	102.00	102.00 X
22	1 REAR FLOOR BOARD <i>waged</i>	432.00	432.00 ✓
23	1 REAR FLOOR COMPARTMENT PANEL <i>R</i>	1,260.00	1,260.00 X
24	1 REAR FENDER RH <i>R</i>	1,685.00	1,685.00 X
25	2 REAR FENDER INNER TRIMS <i>ols del/waged</i> <i>also 11</i>	289.00	578.00 <i>1pc</i>
26	1 REAR FENDER INNER TRIMS CLIPS <i>nee</i>	4.50	45.00 ✓
27	2 REAR FENDER INNER SHIELDS RH/LH <i>11</i>	82.00	164.00 X
28	2 REAR TAILLAMPS RH/LH <i>one</i> <i>425x25 810</i>	482.00	964.00 ✓
29	2 REAR TAILLAMPS PANELS RH/LH <i>R</i>	115.00	230.00 X
			10,640.00
Less 10%			1,064.00
			9,576.00

SPECIAL NETT ITEMS

1	1 (SET) REAR REVERSE SENSOR <i>showd</i>	280.00	280.00 <i>200</i>
2	1 (SET) REAR FLOOR COMPARTMENT SOUND PROOFING <i>nee</i>	150.00	150.00 ✓
			430.00

LABOUR CHARGES :

1	TO CHECK REAR ELECTRICAL WIRING	50.00	30
2	TO REMOVE & REFIX INTERIOR TRIMS TO ASSIST REPAIR	120.00	80
3	TO REMOVE & REPLACE EXHAUST SYSTEM	100.00	60
4	TO REMOVE AND REPLACE REVERSE SENSORS	60.00	50
5	TO TUFF KOTE	120.00	60
6	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	1,200.00	1100
7	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	1,600.00	1000
		<u>3,250.00</u>	

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 13,256.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5736
108
P-516240
S.N-350
L-2380
78924
6313