

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	📄 ✓	🖨	Find Next
---	---	----------	---	---	---	---	--------	-----	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSG INSURANCE (S) PTE LTD		Ref: CS/MSG21011106/Bqf3	
4 SHENTON WAY #21-01		Date: 01/11/2021	
SGX CENTRE 2 SINGAPORE 068807		Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBH 956B	Veh. Inspected	SKF 8517L
Policy No.	MSD/VMT/21-513972-WTT	Coverage (\$)	0.00
Claim No.	MSC/V/21-000470	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY MEI LING)	Assign Date	01/11/2021
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/10/2021	Inspection Date	01/11/2021
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			