

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: AXA INSURANCE	DATE	: 01/11/2021
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMC8521R		
MODEL	: HYUNDAI ELANTRA AD 1.6 GLS AT (AMS)		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 28-Oct-21
		TIME	: 20:00HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

KMH D841CMJ4727824

Asher.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>tern</i>	1	\$ 650.20	\$ 650.20
2	FRONT BUMPER SIDE RETAINER <i>2nd</i>	1	\$ 62.40	\$ 62.40
3	FRONT BUMPER FOGLAMP RH <i>3 Cudd</i>	1	\$ 280.00	\$ 280.00
4	FRONT BUMPER FOGLAMP HOUSING RH <i>the face</i>	1	\$ 155.60	\$ 155.60
5	FRONT BUMPER DAYLIGHT	1	\$ 355.20	\$ 355.20
6	HEADLAMP RH <i>Cudd.</i>	1	\$ 1,080.50	\$ 1,080.50
7	HEADLAMP LOWER BRACKET RH <i>Not New</i>	1	\$ 90.50	\$ 90.50
8	FRONT FENDER RH <i>Repair</i>	1	\$ 530.50	\$ 530.50
9	FRONT FENDER INNER COWLING RH <i>tern</i>	1	\$ 130.50	\$ 130.50
10	FRONT KNUCKLE ARM RH <i>2</i>	1	\$ 366.90	\$ 366.90
11	FRONT KNUCKLE BEARING RH <i>new</i>	1	\$ 180.00	\$ 180.00
12	FRONT LOWER ARM RH <i>new</i>	1	\$ 302.00	\$ 302.00
13	FRONT SUPPORT PANEL <i>Not New</i>	1	\$ 1,030.00	\$ 1,030.00

TOTAL PRICE \$ 5,214.30

LESS 20% \$ 1,042.86

SUB TOTAL PRICE \$ 4,171.44

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-----	-------------	-----	-------------	--------------

1	FRONT BUMPER CLIP(SET) <i>Nu</i>	1	\$ 20.00	\$ 20.00
2	FRONT FENDER INNER COWLING CLIPS(SET) <i>Nu</i>	1	\$ 20.00	\$ 20.00
3	WHEEL RIM <i>lit</i>	1	\$ 1,200.00	\$ 1,200.00

420

TOTAL \$ 1,240.00

380

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	<i>300</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>400</i>	
3	WIRING CHECK	\$ 120.00	<i>30</i>	
4	REFOCUS HEADLAMP BEAM	\$ 80.00	<i>x</i>	
5	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 280.00	<i>x</i>	
6	FOUR WHEEL ALIGHMENT	\$ 100.00	<i>80</i>	

8/0

TOTAL \$ 2,980.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,411.44
TOTAL LABOUR COST : \$ 2,980.00
TOTAL REPAIR COST : \$ 8,391.44

total: 2830
L/S: 2250
03 days

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: