

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	📄 ✓	🖨	Find Next
---	---	----------	---	---	---	---	--------	-----	---	----------------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877			Ref: CS/FCI21011197/Evf3 Date: 02/11/2021 Code: FCI2	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		XE 2870G	
Policy No.	Coverage (\$)		0.00	
Claim No.	D21003069MFVS	Excess (\$)	3,000.00	
Assign From	ESTHER LIM	Assign Date	02/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/10/2021	Inspection Date	03/11/2021	
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				